

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71863
Work Order: 10801398_01

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	840 THRESHER, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/04/2021 15:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	08/11/2021 13:32
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71864
Work Order: 10801398_02

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	840 THRESHER, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/04/2021 15:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	08/11/2021 13:32
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71865
Work Order: 10801398_03

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	174 HASTINGS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/05/2021 07:30
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	08/11/2021 13:32
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71866
Work Order: 10801398_04

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	174 HASTINGS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/05/2021 07:30
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	08/11/2021 13:32
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71867
Work Order: 10801398_05

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	853 E VINEYARD, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/05/2021 05:56
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	08/11/2021 13:32
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	0.005	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71868
Work Order: 10801398_06

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	853 E VINEYARD, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/05/2021 05:56
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	08/11/2021 13:32
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71869
Work Order: 10801398_07

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	759 BUSS,BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/05/2021 08:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	08/11/2021 13:32
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71870
Work Order: 10801398_08

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	759 BUSS,BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/05/2021 08:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	08/11/2021 13:32
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71871
Work Order: 10801398_09

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	140 BENTON, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/08/2021 07:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	08/11/2021 13:32
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71872
Work Order: 10801398_10

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	140 BENTON, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/08/2021 07:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	08/11/2021 13:32
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71873
Work Order: 10801398_11

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	663 THRESHER, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/03/2021 05:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	08/11/2021 13:32
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71874
Work Order: 10801398_12

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	663 THRESHER, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/03/2021 05:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	08/11/2021 13:32
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71875
Work Order: 10801398_13

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	446 PACKARD, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/03/2021 07:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	08/11/2021 13:32
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71876
Work Order: 10801398_14

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	446 PACKARD, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/03/2021 07:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	08/11/2021 13:33
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71877
Work Order: 10801398_15

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	141 N WINANS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/04/2021 06:24
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	08/11/2021 13:33
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71878
Work Order: 10801398_16

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	141 N WINANS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/04/2021 06:24
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	08/11/2021 13:33
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71879
Work Order: 10801398_17

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1267 SUPERIOR, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/06/2021 07:35
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	08/11/2021 13:33
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	0.012	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71880
Work Order: 10801398_18

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1267 SUPERIOR, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/06/2021 07:35
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	08/11/2021 13:33
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	0.021	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71881
Work Order: 10801398_19

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	789 THRESHER, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/05/2021 18:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	08/11/2021 13:33
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71882
Work Order: 10801398_20

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	789 THRESHER, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/05/2021 18:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	08/11/2021 13:33
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71883
Work Order: 10801398_21

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	931 MONROE, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/09/2021 06:15
Sample Point:	BATHROOM SINK FIRST DRAW	Date Received:	08/11/2021 13:33
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	0.011	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71884
Work Order: 10801398_22

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	931 MONROE, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/09/2021 06:15
Sample Point:	BATHROOM SINK FIFTH DRAW	Date Received:	08/11/2021 13:33
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	0.017	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71885
Work Order: 10801398_23

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	596 CASS,BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/06/2021 08:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	08/11/2021 13:33
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71886
Work Order: 10801398_24

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	596 CASS,BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/06/2021 08:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	08/11/2021 13:33
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71887
Work Order: 10801398_25

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	610 SUPERIOR, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/06/2021 04:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	08/11/2021 13:33
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71888
Work Order: 10801398_26

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	610 SUPERIOR,BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/06/2021 04:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	08/11/2021 13:33
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71889
Work Order: 10801398_27

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	534 E MAIN ST, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/04/2021 05:45
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	08/11/2021 13:33
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71890
Work Order: 10801398_28

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	534 E MAIN ST, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/04/2021 05:45
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	08/11/2021 13:33
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71891
Work Order: 10801398_29

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	857 OGDEN, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/06/2021 08:30
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	08/11/2021 13:33
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	0.012	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71892
Work Order: 10801398_30

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	857 OGDEN, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/06/2021 08:30
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	08/11/2021 13:33
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	0.015	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71893
Work Order: 10801398_31

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	191 SEARLES, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/04/2021 03:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	08/11/2021 13:33
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71894
Work Order: 10801398_32

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	191 SEARLES, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/04/2021 03:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	08/11/2021 13:33
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71895
Work Order: 10801398_33

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	261 SEARLES, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/03/2021 11:45
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	08/11/2021 13:33
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Aug 13 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ71896
Work Order: 10801398_34

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	261 SEARLES, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/03/2021 11:45
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	08/11/2021 13:33
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/12/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	08/12/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 3 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ74829
Work Order: 10803333_01

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	810 NATE WELLS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/16/2021 18:15
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	08/25/2021 15:44
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/30/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	08/30/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 3 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ74830
Work Order: 10803333_02

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	810 NATE WELLS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/16/2021 18:15
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	08/25/2021 15:44
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/30/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	08/30/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 3 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ74831
Work Order: 10803333_03

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	142 SEARLES, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/12/2021 09:36
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	08/25/2021 15:44
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/30/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	08/30/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 3 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ74832
Work Order: 10803333_04

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	142 SEARLES, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/12/2021 09:36
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	08/25/2021 15:44
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/30/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	08/30/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 3 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ74833
Work Order: 10803333_05

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1022 HURD, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/13/2021 07:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	08/25/2021 15:44
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/30/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	08/30/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 3 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ74834
Work Order: 10803333_06

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1022 HURD, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/13/2021 07:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	08/25/2021 15:44
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/30/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	08/30/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 3 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ74835
Work Order: 10803333_07

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	753 BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/17/2021 08:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	08/25/2021 15:44
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/30/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	08/30/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 3 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ74836
Work Order: 10803333_08

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	753 BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/17/2021 08:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	08/25/2021 15:44
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/30/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	08/30/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 3 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ74837
Work Order: 10803333_09

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1291 SUPERIOR, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/19/2021 09:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	08/25/2021 15:44
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/30/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	08/30/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 3 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ74838
Work Order: 10803333_10

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1291 SUPERIOR, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/19/2021 09:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	08/25/2021 15:44
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/30/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	08/30/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 3 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ74839
Work Order: 10803333_11

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	759 OGDEN, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/16/2021 10:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	08/25/2021 15:44
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/30/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	08/30/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 3 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ74840
Work Order: 10803333_12

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	759 OGDEN, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/16/2021 10:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	08/25/2021 15:44
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/30/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	08/30/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 3 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ74841
Work Order: 10803333_13

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	504 TERRITORIAL, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/17/2021 08:30
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	08/25/2021 15:44
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/30/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	08/30/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 3 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ74842
Work Order: 10803333_14

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	504 TERRITORIAL, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/17/2021 08:30
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	08/25/2021 15:44
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/30/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	08/30/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 3 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ74843
Work Order: 10803333_15

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1057 MONROE, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/17/2021 08:00
Sample Point:	BATHROOM SINK FIRST DRAW	Date Received:	08/25/2021 15:44
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/30/2021	1.3	EPA 200.8	7440-50-8
Lead	0.012	mg/L	0.001	08/30/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 3 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ74844
Work Order: 10803333_16

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1057 MONROE, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/17/2021 08:00
Sample Point:	BATHROOM SINK FIFTH DRAW	Date Received:	08/25/2021 15:44
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/30/2021	1.3	EPA 200.8	7440-50-8
Lead	0.010	mg/L	0.001	08/30/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 3 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ74845
Work Order: 10803333_17

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	846 EDGE CUMBE, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/17/2021 06:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	08/25/2021 15:44
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/30/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	08/30/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 3 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ74846
Work Order: 10803333_18

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	846 EDGE CUMBE, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/17/2021 06:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	08/25/2021 15:44
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/30/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	08/30/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 3 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ74847
Work Order: 10803333_19

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	807 HIGH ST, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/13/2021 11:30
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	08/25/2021 15:44
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/30/2021	1.3	EPA 200.8	7440-50-8
Lead	0.019	mg/L	0.001	08/30/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 3 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ74848
Work Order: 10803333_20

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	807 HIGH ST, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/13/2021 11:30
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	08/25/2021 15:44
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	08/30/2021	1.3	EPA 200.8	7440-50-8
Lead	0.008	mg/L	0.001	08/30/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 10 2021
EGLE-DWERD-CWS-CCO

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ75973
Work Order: 10900147_01

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	781 BUSS,BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/26/2021 06:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	09/01/2021 15:22
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/02/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	09/02/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 10 2021
EGLE-DWERD-CWSS-LCC

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ75974
Work Order: 10900147_02

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	781 BUSS,BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/26/2021 06:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	09/01/2021 15:22
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/02/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	09/02/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 10 2021
EGLE-DWERD-CWS-CCO

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ75975
Work Order: 10900147_03

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	285 HASTINGS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/01/2021 06:30
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	09/01/2021 15:22
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/02/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	09/02/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 10 2021
EGLE-DWERD-CWS-CCO

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ75976
Work Order: 10900147_04

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	285 HASTINGS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/01/2021 06:30
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	09/01/2021 15:22
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/02/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	09/02/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 10 2021
EGLE-DWERD-CWS-CCO

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ75977
Work Order: 10900147_05

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	166 SEARLES, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/01/2021 05:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	09/01/2021 15:22
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/02/2021	1.3	EPA 200.8	7440-50-8
Lead	0.048	mg/L	0.001	09/02/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 10 2021
EGLE-DWERD-CWS-CCO

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ75978
Work Order: 10900147_06

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	166 SEARLES, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/01/2021 05:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	09/01/2021 15:22
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/02/2021	1.3	EPA 200.8	7440-50-8
Lead	0.019	mg/L	0.001	09/02/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 10 2021
EGLE-DWERD-CWS-CCO

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ75979
Work Order: 10900147_07

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	185 PARKER AVE, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/01/2021 05:15
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	09/01/2021 15:22
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/02/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	09/02/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 10 2021
EGLE-DWERD-CWS-CCO

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ75980
Work Order: 10900147_08

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	185 PARKER AVE, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/01/2021 05:15
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	09/01/2021 15:22
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/02/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	09/02/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 10 2021
EGLE-DWERD-CWS-CCO

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ75981
Work Order: 10900147_09

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	265 SEARLES, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/24/2021 01:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	09/01/2021 15:22
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/02/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	09/02/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 10 2021
EGLE-DWERD-CWS-CCO

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ75982
Work Order: 10900147_10

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	265 SEARLES, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/24/2021 01:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	09/01/2021 15:22
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/02/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	09/02/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 10 2021
EGLE-DWERD-CWS-CCO

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ75983
Work Order: 10900147_11

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	150 PARKER AVE, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/01/2021 07:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	09/01/2021 15:23
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/02/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	09/02/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 10 2021
EGLE-DWERD-CWS-CCO

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ75984
Work Order: 10900147_12

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	150 PARKER AVE, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/01/2021 07:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	09/01/2021 15:23
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/02/2021	1.3	EPA 200.8	7440-50-8
Lead	0.008	mg/L	0.001	09/02/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 10 2021
EGLE-DWERD-CWSS-LCC

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ75985
Work Order: 10900147_13

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1198 JENNINGS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/17/2021 08:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	09/01/2021 15:23
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

Sample Comment LJ75985 EPA requires samples for metals analysis to be acidified within 14 days of collection for compliance monitoring. This sample was received more than 14 days after collection.

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/02/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	09/02/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 10 2021
EGLE-DWERD-CWSS-LCC

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ75986
Work Order: 10900147_14

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1198 JENNINGS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/17/2021 08:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	09/01/2021 15:23
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

Sample Comment LJ75986 EPA requires samples for metals analysis to be acidified within 14 days of collection for compliance monitoring. This sample was received more than 14 days after collection.

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/02/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	09/02/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 10 2021
EGLE-DWERD-CWS-CCO

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ75987
Work Order: 10900147_15

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	277 HASTINGS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/01/2021 07:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	09/01/2021 15:23
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/02/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	09/02/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 10 2021
EGLE-DWERD-CWS-CCO

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ75988
Work Order: 10900147_16

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	277 HASTINGS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/01/2021 07:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	09/01/2021 15:23
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/02/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	09/02/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 10 2021
EGLE-DWERD-CWS-CCO

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ75989
Work Order: 10900147_17

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	127 SEARLES, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/27/2021 08:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	09/01/2021 15:23
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/02/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	09/02/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 10 2021
EGLE-DWERD-CWSS-LCC

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ75990
Work Order: 10900147_18

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	127 SEARLES, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	08/27/2021 08:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	09/01/2021 15:23
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/02/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	09/02/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 15 2021
EGLE-DWEHD-CWSS-LOU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ76950
Work Order: 10900866_01

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	946 BISHOP, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/02/2021 08:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	09/08/2021 16:11
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/10/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	09/10/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
[Sep 15 2021]
EGLE-DWEHD-CWSS-LOU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ76951
Work Order: 10900866_02

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	946 BISHOP, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/02/2021 08:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	09/08/2021 16:11
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/10/2021	1.3	EPA 200.8	7440-50-8
Lead	0.005	mg/L	0.001	09/10/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED

Sep 27 2021

EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: **LJ79067**
Work Order: 10902260_01

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1133 JENNINGS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/14/2021 06:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	09/17/2021 11:17
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/20/2021	1.3	EPA 200.8	7440-50-8
Lead	0.012	mg/L	0.001	09/20/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 27 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: **LJ79068**
Work Order: 10902260_02

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1133 JENNINGS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/14/2021 06:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	09/17/2021 11:17
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/20/2021	1.3	EPA 200.8	7440-50-8
Lead	0.020	mg/L	0.001	09/20/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED

Sep 27 2021

EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: **LJ79069**
Work Order: 10902260_03

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	875 MCGUIGAN AVE, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/14/2021 05:00
Sample Point:	BATHROOM SINK FIRST DRAW	Date Received:	09/17/2021 11:17
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/20/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	09/20/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED

Sep 27 2021

EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: **LJ79070**
Work Order: **10902260_04**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	875 MCGUIGAN AVE, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/14/2021 05:00
Sample Point:	BATHROOM SINK FIFTH DRAW	Date Received:	09/17/2021 11:17
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/20/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	09/20/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED

Sep 27 2021

EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: **LJ79071**
Work Order: **10902260_05**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1129 JENNINGS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/14/2021 07:15
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	09/17/2021 11:17
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/20/2021	1.3	EPA 200.8	7440-50-8
Lead	0.011	mg/L	0.001	09/20/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED

Sep 27 2021

EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: **LJ79072**
Work Order: **10902260_06**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1129 JENNINGS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/14/2021 07:15
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	09/17/2021 11:17
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/20/2021	1.3	EPA 200.8	7440-50-8
Lead	0.015	mg/L	0.001	09/20/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED

Sep 27 2021

EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: **LJ79073**
Work Order: 10902260_07

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1354 BISHOP, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/14/2021 05:05
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	09/17/2021 11:17
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/20/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	09/20/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED

Sep 27 2021

EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: **LJ79074**
Work Order: 10902260_08

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1354 BISHOP, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/14/2021 05:05
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	09/17/2021 11:17
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/20/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	09/20/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 30 2021
EGLE DRINKING WATER

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ79985
Work Order: 10902908_01

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1161 UNION 1ST LITER, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/15/2021 06:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	09/22/2021 15:21
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.007	mg/L	0.001	09/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 30 2021
EGL-DRINKING-WATER

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ79986
Work Order: 10902908_02

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1161 UNION 5TH LITER, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/15/2021 06:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	09/22/2021 15:21
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.005	mg/L	0.001	09/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 30 2021
EGLE DRINKING WATER LAB

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ79987
Work Order: 10902908_03

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1292 BISHOP 1ST LITER, BENTON HARBO	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/17/2021 07:11
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	09/22/2021 15:21
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	09/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 30 2021
EGLE DRINKING WATER LAB

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ79988
Work Order: 10902908_04

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1292 BISHOP 5TH LITER, BENTON HARBO	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/17/2021 07:11
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	09/22/2021 15:21
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	09/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 30 2021
EGLE DRINKING WATER

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ79989
Work Order: 10902908_05

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1212 PEARL 1ST LITER, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/17/2021 15:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	09/22/2021 15:22
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	09/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 30 2021
EGLE DRINKING WATER LAB

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ79990
Work Order: 10902908_06

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1212 PEARL 5TH LITER, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/17/2021 15:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	09/22/2021 15:22
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	09/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 30 2021
EGLE DRINKING WATER

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ79991
Work Order: 10902908_07

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1110 OGDEN 1ST LITER,BENTON HARBOF	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/20/2021 05:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	09/22/2021 15:22
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.007	mg/L	0.001	09/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 30 2021
EGLE DRINKING WATER

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ79992
Work Order: 10902908_08

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1110 OGDEN 5TH LITER, BENTON HARBOF	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/20/2021 05:00
Sample Point:	KITCHEN SINK FIFTH LITER	Date Received:	09/22/2021 15:22
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	09/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 30 2021
EGLE DRINKING WATER LAB

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ79993
Work Order: 10902908_09

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	932 SUPERIOR 1ST LITER, BENTON HARB	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/16/2021 08:00
Sample Point:	BATHROOM SINK FIRST DRAW	Date Received:	09/22/2021 15:22
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	09/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 30 2021
EGLE DRINKING WATER LAB

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ79994
Work Order: 10902908_10

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	932 SUPERIOR 5TH LITER,BENTON HARB	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/16/2021 08:00
Sample Point:	BATHROOM SINK FIFTH DRAW	Date Received:	09/22/2021 15:22
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	09/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 30 2021

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ79995
Work Order: 10902908_11

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1088 OGDEN 1ST LITER, BENTON HARBO	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/16/2021 07:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	09/22/2021 15:22
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	09/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 30 2021
EGL-DRINKING-WATER

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ79996
Work Order: 10902908_12

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1088 OGDEN 5TH LITER, BENTON HARBO	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/16/2021 07:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	09/22/2021 15:22
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	09/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 30 2021
EGLE DRINKING WATER

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ79997
Work Order: 10902908_13

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	114 MCCORD 1ST LITER, BENTON HARBO	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/14/2021 14:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	09/22/2021 15:22
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	09/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Sep 30 2021
EGLE DRINKING WATER

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ79998
Work Order: 10902908_14

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	114 MCCORD 5TH LITER, BENTON HARBO	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	09/14/2021 14:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	09/22/2021 15:22
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	09/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	09/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Oct 11 2021
EGLE-DWEND-CWSS-LCU

Report To: ROBERT JONES
601 RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ83329
Work Order: 11000689_01

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1118 BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/06/2021 09:15
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	10/06/2021 15:36
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	10/07/2021	1.3	EPA 200.8	7440-50-8
Lead	0.013	mg/L	0.001	10/07/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Oct 11 2021
EGLE-DWEND-CWSS-LCU

Report To: ROBERT JONES
601 RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ83330
Work Order: 11000689_02

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1118 BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/06/2021 09:15
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	10/06/2021 15:36
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	10/07/2021	1.3	EPA 200.8	7440-50-8
Lead	0.010	mg/L	0.001	10/07/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report



Report To: ROBERT JONES
601 RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ83331
Work Order: 11000689_03

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1069 AGARD, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/06/2021 06:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	10/06/2021 15:36
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	10/07/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	10/07/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report



Report To: ROBERT JONES
601 RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ83332
Work Order: 11000689_04

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1069 AGARD, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/06/2021 06:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	10/06/2021 15:36
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	10/07/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	10/07/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Oct 11 2021
EGLE-DWEND-CWSIS-LCU

Report To: ROBERT JONES
601 RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ83333
Work Order: 11000689_05

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1124 COLFAX, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/06/2021 04:30
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	10/06/2021 15:36
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	10/07/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	10/07/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Oct 11 2021
EGLE-DWEND-CWSS-LCU

Report To: ROBERT JONES
601 RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ83334
Work Order: 11000689_06

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1124 COLFAX, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/06/2021 04:30
Sample Point:	KITCHEN SINK FIFTH	Date Received:	10/06/2021 15:36
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	10/07/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	10/07/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Oct 11 2021
EGLE-DWEND-CWSS-LCU

Report To: ROBERT JONES
601 RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ83335
Work Order: 11000689_07

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1178 BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/06/2021 08:25
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	10/06/2021 15:36
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	10/07/2021	1.3	EPA 200.8	7440-50-8
Lead	0.010	mg/L	0.001	10/07/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Oct 11 2021
EGLE-DWEND-CWSIS-LCU

Report To: ROBERT JONES
601 RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ83336
Work Order: 11000689_08

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1178 BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/06/2021 08:25
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	10/06/2021 15:36
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	10/07/2021	1.3	EPA 200.8	7440-50-8
Lead	0.008	mg/L	0.001	10/07/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Oct 19 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ84253
Work Order: 11001273_01

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1248 BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/07/2021 11:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	10/13/2021 15:29
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	10/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.005	mg/L	0.001	10/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Oct 19 2021
EGLE-DWEND-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ84254
Work Order: 11001273_02

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1248 BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/07/2021 11:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	10/13/2021 15:29
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	10/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	10/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Oct 19 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ84255
Work Order: 11001273_03

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1244 JENNINGS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/07/2021 17:30
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	10/13/2021 15:29
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	10/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	10/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Oct 19 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ84256
Work Order: 11001273_04

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1244 JENNINGS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/07/2021 17:30
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	10/13/2021 15:29
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	10/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	10/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Oct 19 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ84257
Work Order: 11001273_05

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	578 EDWARDS,BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/06/2021 12:00
Sample Point:	BATHROOM SINK FIFTH DRAW	Date Received:	10/13/2021 15:29
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	10/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	10/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Oct 19 2021
EGLE-DWHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ84258
Work Order: 11001273_06

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	578 EDWARDS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/06/2021 12:00
Sample Point:	BATHROOM SINK FIRST DRAW	Date Received:	10/13/2021 15:29
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	10/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	10/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report



Report To: ROBERT JONES
601 RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ83331
Work Order: 11000689_03

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1069 HURD, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/06/2021 06:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	10/06/2021 15:36
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

Sample Comment LJ83331 Corrected report. Disregard previous report for this sample number.

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	10/07/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	10/07/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report



Report To: ROBERT JONES
601 RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ83332
Work Order: 11000689_04

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1069 HURD, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/06/2021 06:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	10/06/2021 15:36
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

Sample Comment LJ83332 Corrected report. Disregard previous report for this sample number.

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	10/07/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	10/07/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ86267
Work Order: 11002624_01

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1191 PAVONE, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/20/2021 08:00
Sample Point:	BATHROOM SINK FIRST DRAW	Date Received:	10/27/2021 15:43
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	10/28/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	10/28/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ86268
Work Order: 11002624_02

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1191 PAVONE, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/20/2021 08:00
Sample Point:	BATHROOM SINK FIFTH DRAW	Date Received:	10/27/2021 15:43
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	10/28/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	10/28/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ86269
Work Order: 11002624_03

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	792 BRITAIN, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/19/2021 07:30
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	10/27/2021 15:43
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	10/28/2021	1.3	EPA 200.8	7440-50-8
Lead	0.005	mg/L	0.001	10/28/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ86270
Work Order: 11002624_04

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	792 BRITAIN, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/19/2021 07:30
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	10/27/2021 15:43
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	10/28/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	10/28/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ86271
Work Order: 11002624_05

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	846 E BRITAIN, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/19/2021 12:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	10/27/2021 15:43
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	10/28/2021	1.3	EPA 200.8	7440-50-8
Lead	0.008	mg/L	0.001	10/28/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ86272
Work Order: 11002624_06

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	846 E BRITAIN, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/19/2021 12:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	10/27/2021 15:43
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	10/28/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	10/28/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ86273
Work Order: 11002624_07

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1259 BISHOP, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/20/2021 06:35
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	10/27/2021 15:43
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	10/28/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	10/28/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ86274
Work Order: 11002624_08

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1259 BISHOP, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/20/2021 06:35
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	10/27/2021 15:43
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	10/28/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	10/28/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ86275
Work Order: 11002624_09

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1066 MONROE, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/19/2021 04:30
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	10/27/2021 15:43
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	10/28/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	10/28/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ86276
Work Order: 11002624_10

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1066 MONROE, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/19/2021 04:30
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	10/27/2021 15:43
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	10/28/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	10/28/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ86277
Work Order: 11002624_11

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	812 LAVETTE, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/19/2021 11:30
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	10/27/2021 15:43
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	10/28/2021	1.3	EPA 200.8	7440-50-8
Lead	0.009	mg/L	0.001	10/28/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ86278
Work Order: 11002624_12

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	812 LAVETTE, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/19/2021 11:30
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	10/27/2021 15:43
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	10/28/2021	1.3	EPA 200.8	7440-50-8
Lead	0.018	mg/L	0.001	10/28/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Nov 8 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ87271
Work Order: 11100408_01

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1161 UNION, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/27/2021 19:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	11/03/2021 14:41
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	11/04/2021	1.3	EPA 200.8	7440-50-8
Lead	0.014	mg/L	0.001	11/04/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Nov 8 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ87272
Work Order: 11100408_02

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1161 UNION, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	10/27/2021 19:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	11/03/2021 14:41
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	11/04/2021	1.3	EPA 200.8	7440-50-8
Lead	0.011	mg/L	0.001	11/04/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Nov 22 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ88344
Work Order: 11101137_01

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	819 E VINEYARD, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	11/05/2021 07:00
Sample Point:	BATHROOM SINK FIRST DRAW	Date Received:	11/10/2021 15:27
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	11/17/2021	1.3	EPA 200.8	7440-50-8
Lead	0.005	mg/L	0.001	11/17/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Nov 22 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ88345
Work Order: 11101137_02

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	819 E VINEYARD, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	11/05/2021 07:00
Sample Point:	BATHROOM SINK FIFTH DRAW	Date Received:	11/10/2021 15:27
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	11/17/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	11/17/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Nov 22 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ88346
Work Order: 11101137_03

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	754 LAVETTE, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	11/04/2021 06:00
Sample Point:	BATHROOM SINK FIRST DRAW	Date Received:	11/10/2021 15:27
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.06	mg/L	0.05	11/17/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	11/17/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

Official Laboratory Report

RECEIVED
Nov 22 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ88347
Work Order: 11101137_04

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	754 LAVETTE, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	11/04/2021 06:00
Sample Point:	BATHROOM SINK FIFTH DRAW	Date Received:	11/10/2021 15:27
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	11/17/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	11/17/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit	mg/L: milligrams / Liter (ppm)	CFU: Colony Forming Unit
MCL: Maximum Contaminant Level	ng/L: nanograms / Liter (ppt)	CAS: Chemical Abstract Service
AL: Action Level	MPN: Most Probable Number	Laboratory Contact: Marlene Kane
Not Detected: Not detected at or above the reporting limit (RL)		

ANALYTICAL REPORT

Eurofins Eaton Analytical - South Bend
110 S Hill Street
South Bend, IN 46617
Tel: (574)233-4777

Laboratory Job ID: 810-4136-1
Client Project/Site: City of Benton Harbor

For:
City of Benton Harbor
601 Ridgeway
St Joseph, Michigan 49085

Attn: Abul Ahmed



Authorized for release by:
10/21/2021 3:38:41 PM
Urvashi Patel, Client Service Manager
Urvashi.Patel@Eurofinset.com

Designee for
Patricia Muff, Project Manager
(574)233-4777
patricia.muff@eurofinset.com

LINKS

Review your project
results through
Total Access

Have a Question?



Visit us at:
www.eurofinsus.com/Env

This report has been electronically signed and authorized by the signatory. Electronic signature is intended to be the legally binding equivalent of a traditionally handwritten signature.

Results relate only to the items tested and the sample(s) as received by the laboratory.

RECEIVED
Nov 29 2021
EGL-0WEHD-CWSS-LCU



Table of Contents

Cover Page	1
Table of Contents	2
Definitions/Glossary	3
Case Narrative	4
Client Sample Results	5
Lab Chronicle	6
Certification Summary	7
Method Summary	8
Sample Summary	9
Chain of Custody	10
Receipt Checklists	11



Definitions/Glossary

Client: City of Benton Harbor
Project/Site: City of Benton Harbor

Job ID: 810-4136-1

Glossary

Abbreviation	These commonly used abbreviations may or may not be present in this report.
α	Listed under the "D" column to designate that the result is reported on a dry weight basis
%R	Percent Recovery
CFL	Contains Free Liquid
CFU	Colony Forming Unit
CNF	Contains No Free Liquid
DER	Duplicate Error Ratio (normalized absolute difference)
Dil Fac	Dilution Factor
DL	Detection Limit (DoD/DOE)
DL, RA, RE, IN	Indicates a Dilution, Re-analysis, Re-extraction, or additional Initial metals/anion analysis of the sample
DLC	Decision Level Concentration (Radiochemistry)
EDL	Estimated Detection Limit (Dioxin)
LOD	Limit of Detection (DoD/DOE)
LOQ	Limit of Quantitation (DoD/DOE)
MCL	EPA recommended "Maximum Contaminant Level"
MDA	Minimum Detectable Activity (Radiochemistry)
MDC	Minimum Detectable Concentration (Radiochemistry)
MDL	Method Detection Limit
ML	Minimum Level (Dioxin)
MPN	Most Probable Number
MQL	Method Quantitation Limit
NC	Not Calculated
ND	Not Detected at the reporting limit (or MDL or EDL if shown)
NEG	Negative / Absent
POS	Positive / Present
PQL	Practical Quantitation Limit
PRES	Presumptive
QC	Quality Control
RER	Relative Error Ratio (Radiochemistry)
RL	Reporting Limit or Requested Limit (Radiochemistry)
RPD	Relative Percent Difference, a measure of the relative difference between two points
TEF	Toxicity Equivalent Factor (Dioxin)
TEQ	Toxicity Equivalent Quotient (Dioxin)
TNTC	Too Numerous To Count

1
2
3
4
5
6
7
8
9
10
11

RECEIVED
Nov 29 2021
EGL-DEHD-CWSS-LCU

Case Narrative

Client: City of Benton Harbor
Project/Site: City of Benton Harbor

Job ID: 810-4136-1

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11

Job ID: 810-4136-1

Laboratory: Eurofins Eaton Analytical - South Bend

Narrative

Job Narrative
810-4136-1

Comments

No additional comments.

Receipt

The samples were received on 10/5/2021 11:06 AM. Unless otherwise noted below, the samples arrived in good condition, and where required, properly preserved and on ice.

Metals

No analytical or quality issues were noted, other than those described in the Definitions/Glossary page.

RECEIVED
Nov 29 2021
EGL-DEHD-CWSS-LCU

Client Sample Results

Client: City of Benton Harbor
Project/Site: City of Benton Harbor

Job ID: 810-4136-1

Client Sample ID: 232 Hastings 1st Draw

Date Collected: 10/01/21 16:00

Date Received: 10/05/21 11:06

Lab Sample ID: 810-4136-1

Matrix: Drinking Water

PWSID Number: MI600

Method: 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	4.5		1.0	ug/L			10/14/21 12:47	1
Copper	<1.0		1.0	ug/L			10/14/21 12:47	1

Client Sample ID: 232 Hastings 5th Draw

Date Collected: 10/01/21 16:00

Date Received: 10/05/21 11:06

Lab Sample ID: 810-4136-2

Matrix: Drinking Water

PWSID Number: MI600

Method: 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	2.7		1.0	ug/L			10/14/21 12:50	1
Copper	<1.0		1.0	ug/L			10/14/21 12:50	1

Client Sample ID: 1020 Bishop 1st Draw

Date Collected: 09/21/21 05:00

Date Received: 10/05/21 11:06

Lab Sample ID: 810-4136-3

Matrix: Drinking Water

PWSID Number: MI600

Method: 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<1.0		1.0	ug/L			10/14/21 12:57	1
Copper	1.4		1.0	ug/L			10/14/21 12:57	1

Client Sample ID: 1020 Bishop 5th Draw

Date Collected: 09/21/21 05:00

Date Received: 10/05/21 11:06

Lab Sample ID: 810-4136-4

Matrix: Drinking Water

PWSID Number: MI600

Method: 200.8 - Metals (ICP/MS)

Analyte	Result	Qualifier	RL	Unit	D	Prepared	Analyzed	Dil Fac
Lead	<1.0		1.0	ug/L			10/14/21 13:00	1
Copper	3.2		1.0	ug/L			10/14/21 13:00	1

RECEIVED
Nov 29 2021
EGLE-DWHD-CWSS-LCU

Lab Chronicle

Client: City of Benton Harbor
Project/Site: City of Benton Harbor

Job ID: 810-4136-1

Client Sample ID: 232 Hastings 1st Draw

Date Collected: 10/01/21 16:00

Date Received: 10/05/21 11:06

Lab Sample ID: 810-4136-1

Matrix: Drinking Water

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Prepared or Analyzed	Analyst	Lab
Total/NA	Analysis	200.8		1	5291	10/14/21 12:47	NB	EA SB

Client Sample ID: 232 Hastings 5th Draw

Date Collected: 10/01/21 16:00

Date Received: 10/05/21 11:06

Lab Sample ID: 810-4136-2

Matrix: Drinking Water

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Prepared or Analyzed	Analyst	Lab
Total/NA	Analysis	200.8		1	5291	10/14/21 12:50	NB	EA SB

Client Sample ID: 1020 Bishop 1st Draw

Date Collected: 09/21/21 05:00

Date Received: 10/05/21 11:06

Lab Sample ID: 810-4136-3

Matrix: Drinking Water

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Prepared or Analyzed	Analyst	Lab
Total/NA	Analysis	200.8		1	5291	10/14/21 12:57	NB	EA SB

Client Sample ID: 1020 Bishop 5th Draw

Date Collected: 09/21/21 05:00

Date Received: 10/05/21 11:06

Lab Sample ID: 810-4136-4

Matrix: Drinking Water

Prep Type	Batch Type	Batch Method	Run	Dilution Factor	Batch Number	Prepared or Analyzed	Analyst	Lab
Total/NA	Analysis	200.8		1	5291	10/14/21 13:00	NB	EA SB

Laboratory References:

EA SB = Eurofins Eaton Analytical - South Bend, 110 S Hill Street, South Bend, IN 46617, TEL (574)233-4777

RECEIVED
Nov 29 2021
EGLLE-DWEHD-CWSS-LCU

Accreditation/Certification Summary

Client: City of Benton Harbor
Project/Site: City of Benton Harbor

Job ID: 810-4136-1

Laboratory: Eurofins Eaton Analytical - South Bend

The accreditations/certifications listed below are applicable to this report.

Authority	Program	Identification Number	Expiration Date
Michigan	State	9926	03-22-22

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11



Method Summary

Client: City of Benton Harbor
Project/Site: City of Benton Harbor

Job ID: 810-4136-1

Method	Method Description	Protocol	Laboratory
200.8	Metals (ICP/MS)	EPA	EA SB

Protocol References:

EPA = US Environmental Protection Agency

Laboratory References:

EA SB = Eurofins Eaton Analytical - South Bend, 110 S Hill Street, South Bend, IN 46617, TEL (574)233-4777



Sample Summary

Client: City of Benton Harbor
Project/Site: City of Benton Harbor

Job ID: 810-4136-1

Lab Sample ID	Client Sample ID	Matrix	Collected	Received	PWSID Number
810-4136-1	232 Hastings 1st Draw	Drinking Water	10/01/21 16:00	10/05/21 11:06	MI600
810-4136-2	232 Hastings 5th Draw	Drinking Water	10/01/21 16:00	10/05/21 11:06	MI600
810-4136-3	1020 Bishop 1st Draw	Drinking Water	09/21/21 05:00	10/05/21 11:06	MI600
810-4136-4	1020 Bishop 5th Draw	Drinking Water	09/21/21 05:00	10/05/21 11:06	MI600

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11

RECEIVED
Nov 29 2021
EGL-DEHD-CWSS-LCU



Eaton Analytical



810-4136 Chain of Custody

110 S. Hill Street
South Bend, IN 46617
T: 1.800.332.4345
F: 1.574.233.8207

pm 10/5/21

1224

Order #

Batch #

www.EurofinsUS.com/Eaton

CHAIN OF CUSTODY RECORD

Page ___ of ___

Shaded area for EEA use only

REPORT TO:		SAMPLER (Signature)		PWS ID #	STATE (sample origin)	PROJECT NAME	PO#	# OF CONTAINERS	MATRIX CODE	TURNAROUND TIME
Benton Harbor 5510-5-21		Resident		600	MI	Lead Copper Monitoring				
REPORT TO: rjones@fv-operations.com; dharlan@fv-operations.com				POPULATION SERVED	SOURCE WATER					
BILL TO: drice@bhcity.us		COMPLIANCE MONITORING		9,639	Lake Michigan					
		Yes		No						
		x								

LAB Number	COLLECTION				SAMPLING SITE	TEST NAME	SAMPLE REMARKS	CHLORINATED		# OF CONTAINERS	MATRIX CODE	TURNAROUND TIME
	DATE	TIME	AM	PM				YES	NO			
1	10/01/21	4:00		x	232 Hastings	Lead/Copper PH72	1st Draw	x		1	DW	
2	10/01/21	4:00		x	232 Hastings	Lead/Copper PH72	5th Draw	x		1	DW	
3	09/21/21	5:00	x		1020 Bishop	Lead/Copper PH72 } 55	1st Draw	x		1	DW	
4	09/21/21	5:00	x		1020 Bishop	Lead/Copper PH72 } 10521	5th Draw	x		1	DW	
5												
6												
7												
8												
9												
10												
11												
12												
13												
14												

RELINQUISHED BY: (Signature)	DATE	TIME	RECEIVED BY: (Signature)	DATE	TIME	LAB RESERVES THE RIGHT TO RETURN UNUSED PORTIONS OF NON-AQUEOUS SAMPLES TO CLIENT LAB COMMENTS <h2 style="color: red; text-align: center;">Client Provided Sample Container</h2>
	10/5/21	11:06				
		AM PM			AM PM	
RELINQUISHED BY: (Signature)	DATE	TIME	RECEIVED BY: (Signature)	DATE	TIME	CONDITIONS UPON RECEIPT (check one): <input type="checkbox"/> Iced: Wet/Blue <input checked="" type="checkbox"/> RECEIVED Nov 29 2021 EGLE-DWHD-CWSS-LCU <input type="checkbox"/> °C Upon Receipt <input checked="" type="checkbox"/> N/A
		AM PM			AM PM	
		AM PM			AM PM	
RELINQUISHED BY: (Signature)	DATE	TIME	RECEIVED FOR LABORATORY BY:	DATE	TIME	
		AM PM		10/5/21	11:06	
		AM PM			AM PM	

MATRIX CODES: DW-DRINKING WATER RW-REAGENT WATER GW-GROUND WATER EW-EXPOSURE WATER SW-SURFACE WATER PW-POOL WATER WW-WASTE WATER	TURN-AROUND TIME (TAT) - SURCHARGES SW = Standard Written: (15 working days) 0% RV* = Rush Verbal: (5 working days) 50% RW* = Rush Written: (5 working days) 75%	IV* = Immediate Verbal: (3 working days) 100% IW* = Immediate Written: (3 working days) 125% SP* = Weekend, Holiday CALL STAT* = Less than 48 hours CALL	Samples received unannounced with less than 48 hours holding time remaining may be subject to additional charges.
--	--	---	---

* Please call, expedited service not available for all testing

06-LO-F0435 Issue 6.0 Effective Date: 2016-09-20

Login Sample Receipt Checklist

Client: City of Benton Harbor

Job Number: 810-4136-1

Login Number: 4136

List Source: Eurofins Eaton Analytical - South Bend

List Number: 1

Creator: Spurgeon, Sheri

Question	Answer	Comment
The cooler's custody seal, if present, is intact.	True	
Sample custody seals, if present, are intact.	True	
Samples were received on ice.	False	Thermal preservation not required.
Cooler Temperature is acceptable.	True	
Cooler Temperature is recorded.	False	Thermal preservation not required.
COC is present.	True	
COC is filled out in ink and legible.	True	
COC is filled out with all pertinent information.	True	
There are no discrepancies between the containers received and the COC.	True	
Samples are received within Holding Time (excluding tests with immediate HTs)	True	
Sample containers have legible labels.	True	
Containers are not broken or leaking.	True	
Sample collection date/times are provided.	True	
There is sufficient vol. for all requested analyses, incl. any requested MS/MSDs	True	
Containers requiring zero headspace have no headspace or bubble is <6mm (1/4").	True	
Samples do not require splitting or compositing.	True	
Container provided by EEA	False	Client provided containers

