



GRETCHEN WHITMER
GOVERNOR

STATE OF MICHIGAN
DEPARTMENT OF
ENVIRONMENT, GREAT LAKES, AND ENERGY
LANSING



LIESL EICHLER CLARK
DIRECTOR

August 3, 2021

VIA EMAIL AND U.S. MAIL

Mr. Ellis Mitchell
Benton Harbor
200 Wall Street
Benton Harbor, Michigan 49022

WSSN: 00600
County: Berrien
System: Benton Harbor

Dear Mr. Mitchell:

SUBJECT: Lead and Copper Monitoring - Action Level (AL) Exceedance

The Benton Harbor community water supply's 90th percentile value exceeded the AL for lead during the most recent round of lead and copper monitoring of drinking water taps from January 1 to June 30, 2021, as summarized below.

Contaminant	AL	MCLG*	90 th Percentile Value	Number of Sites Above AL	Range of Sample Results	Typical Source of Contaminant
Lead	15 parts per billion (ppb)	0	24 ppb	11	0 - 889 ppb	Corrosion of household plumbing systems; Service lines that may contain lead; Erosion of natural deposits
Copper	1.3 parts per million (ppm)	1.3	0.1	2	0 – 7.6 ppm	Corrosion of household plumbing systems; Erosion of natural deposits

*MCLG: Maximum contaminant level goal means the level of a contaminant in drinking water below which there is no known or expected risk to health. MCLGs allow for a margin of safety.

An AL exceedance is not a violation, but it triggers other requirements under the administrative rules promulgated under the Michigan Safe Drinking Water Act, 1976 PA 399, as amended (Act 399). Requirements include water quality parameter (WQP) monitoring, source water monitoring, corrosion control treatment, and public education (PE). Please refer to the "Timetable of Upcoming Requirements" for your specific deadlines for each of the following requirements.

Issue a Public Advisory (PA)

An amendment to Act 399 on March 29, 2017, requires a public water supply to issue a PA within three business days from the date of this letter to inform all persons served by the water system about the lead AL exceedance. A template has already been provided to you. Please contact the Michigan Department of Environment, Great Lakes, and Energy (EGLE) if you plan to use broadcast media as your delivery method.

Deliver Consumer Notice of Lead and Copper Results

Thank you for completing this requirement timely.

Distribute PE

Sixty days after the end of the monitoring period that exceeded the AL, deliver PE materials to all consumers.

This material is intended to educate consumers about lead health effects, sources of lead, and steps to minimize exposure. Note that the PE material must include information about the following: The exceedance in your water supply, what you are doing to reduce lead levels, lead service lines in your distribution system, and the history of lead levels in your water supply. A template has already been provided to you.

A sample copy of the final PE material along with a PE distribution certification form must be submitted to EGLE no later than ten days after the PE is due.

Conduct WQP Monitoring

Continue collecting one set of WQP samples every two weeks from each entry point to the distribution system, TP001 (Treatment Plant Tap), and quarterly from ten locations in the distribution system.

The WQP samples shall be analyzed for pH, alkalinity, calcium, conductivity, orthophosphate, chloride, sulfate, and temperature. Temperature and pH are field tests and should be completed at the time of sample collection.

If you use EGLE's laboratory, order bottles by calling 517-335-8184 or by downloading the form EQP 2301 *Bottle Order Form* from Michigan.gov/EGLELab. Click on Drinking Water. The tests are analyzed from one sample bottle per location. Request the analyses using the following test codes:

Test Code	Cost	Bottle Number	Test Description
CORR	\$51.00	33	Conductivity, Alkalinity, Phosphate, and Calcium
R	\$18.00	32,33	Chloride, Sulfate

Conduct Source Water Monitoring

Thank you for completing this requirement on March 16, 2019. Repeat every third year until both lead and copper ALs are met during the entire three-year period.

Minimize Corrosion

Minimize lead and copper in drinking water by reducing corrosion of water pipes and household plumbing that contain lead and copper. This is Benton Harbor's sixth AL exceedance. This is the second round of sampling that Benton Harbor has performed since the corrosion control treatment was adjusted in the spring of 2020. After two rounds of follow-up sampling, the department is required to designate optimal water quality

parameter (OWQP) ranges within six months. This designation will be provided under separate cover (Administrative Rule 325.10604f(2)(e)(v)).

Lead and Copper Monitoring

To show the ALs can be met, collect a lead and copper sample from 60 sites between July 1 and December 31, 2021, and again between January 1 and June 30, 2022.

During the most recent round of monitoring, Benton Harbor collected samples from 17 sites that were not the same sites as previously sampled, not on their Lead and Copper Sampling Plan, and had unknown service line and building plumbing materials. Therefore, these sites cannot be appropriately tiered and remain an unknown risk of lead exposure. To take the most conservative approach to protect public health, EGLE included these sites in the calculation of the 90th percentile for this round of sampling since it resulted in a higher 90th percentile.

However, EGLE will no longer accept such sites for compliance monitoring. All samples must be collected from targeted locations that represent the highest Tier available. Once these sites are identified, verified, and memorialized on an approved Lead and Copper Sampling Plan, the same sites shall be used in each monitoring period unless you can no longer gain entry to the site(s) or the site(s) no longer meets the tiering criteria (Administrative Rule 325.10710a(1)). Since Benton Harbor has lead service lines that serve water to single family homes, all sites sampled must be Tier 1 sites. These sites must have verified service line materials and must be reflected on your Lead and Copper Sampling Plan. Additionally, as discussed in recent meetings, Benton Harbor will be standardizing their sampling processes through training, increased oversight, and QA/QC processes to address these issues. EGLE supports this effort and has provided recommended training materials. Please contact EGLE if you need technical assistance or additional materials.

Within 30 days of learning of results, provide individual lead and copper tap results to people who receive water from sites that were sampled. Even if lead or copper was not detected, all monitoring, reporting, consumer notification, and EGLE certification requirements remain in effect.

Consumer Confidence Report (CCR)

Include this AL exceedance in your CCR, which is due to our office, your customers, and the local health department by July 1, 2022. You may use the table format from the first page of this letter.

Also, because the lead AL was exceeded, include the following health effects language:

Infants and children who drink water containing lead could experience delays in their physical or mental development. Children could show slight deficits in attention span and learning abilities. Adults who drink this water over many years could develop kidney problems or high blood pressure.

Lead Service Line Replacement

Water supplies that exceed the lead AL in a compliance monitoring period and have corrosion control treatment installed must begin to replace lead and galvanized previously connected to lead (GPCL) service lines (Administrative Rule 325.604f(5)).

Benton Harbor's preliminary distribution materials inventory indicates that Benton Harbor has 824 services lines known to contain lead, 571 service lines known to contain GPCL, and 1,616 service lines that are unknown but likely contain lead. This means the city has an initial number of lines that meet the replacement requirement of $824 + 571 + 1,616 = 3,011$. Seven percent of this initial number of service lines is 211 service lines. Between July 1, 2021, and June 30, 2022, Benton Harbor must perform 211 lead, or GPCL, service line replacements.

Benton Harbor, and Abonmarche as their consultant, are inventorying the water system and replacing lead service lines. If these efforts increase the number of known or likely lead or GPCL service lines in your water system, the required service line replace numbers must be adjusted as necessary. Benton Harbor should continue replacing lead or GPCL service lines until they have all been removed. If future sampling is below the AL, Benton Harbor's required replacement rate will transition from seven percent annual replacement to five percent on average annual replacement (Administrative Rule 325.10604f(5-6)).

As of June 14, 2018, Act 399 requires that all public water supplies conducting service line replacements shall replace the lead and galvanized iron pipe previously or currently connected to lead portions of the service line at the water supply's expense. Additionally, partial replacements of service lines that contain lead, or galvanized iron pipe previously connected to lead, are banned unless in conjunction with an emergency repair. Service lines are defined as the pipe from the discharge of the corporation fitting to customer site piping or to the building plumbing at the first shut-off valve inside the building, or 18 inches inside the building, whichever is shorter.

What Happens Next?

If you can show that both lead and copper ALs are met in two consecutive six-month periods, then some of the requirements outlined in this letter will no longer apply.

Timetable of Upcoming Requirements

Complete By	Requirement	Comments
Within three business days	Distribute a PA.	Distribute a PA to inform all persons served by the water supply of the lead AL exceedance. Distribution of the notice must be in a form and manner designed to fit the specific situation and must be reasonably calculated to reach all persons served by the public water supply.
Continue	Collect WQP samples (Entry point to the distribution system)	Collect one set of WQP samples every two weeks from your <u>entry point</u> to the distribution system, TP001 (Treatment Plant Tap).

Complete By	Requirement	Comments
August 29, 2021	Perform PE activities including delivering PE materials to all consumers.	PE required activities are listed in enclosed template and checklist. Repeat every year until the lead AL is met in the most recent round of sampling.
September 8, 2021	Send EGLE certification of PE compliance along with a sample copy of the materials delivered.	Sample certification enclosed. Required whenever PE required.
Between July 1 and December 31, 2021	Collect samples from 60 sites from the distribution system and have them analyzed for lead and copper.	Report the results to EGLE and deliver the consumer notice of individual lead and copper results using the downloadable <i>Lead and Copper Report and Consumer Notice of Lead and Copper Results Certificate</i> . Report due January 10, 2022.
Between July 1 and December 31, 2021	Collect WQP samples (Distribution system)	Collect one set of WQP samples from ten locations in the distribution system quarterly. Analyze the samples for pH, alkalinity, calcium, conductivity, orthophosphate, chloride, sulfate, and temperature.
Between January 1 and June 30, 2022	Collect samples from 60 sites from the distribution system and have them analyzed for lead and copper.	Report the results to EGLE and deliver the consumer notice of individual lead and copper results using the downloadable <i>Lead and Copper Report and Consumer Notice of Lead and Copper Results Certificate</i> . Report due July 10, 2022.
Between January 1 and June 30, 2022	Collect WQP samples (Distribution system)	Collect one set of WQP samples from ten locations in the distribution system quarterly. Analyze the samples for pH, alkalinity, calcium, conductivity, orthophosphate, chloride, sulfate, and temperature.
March 31, 2022	Collect one lead and copper sample from your entry point to the distribution system, TP001 (Treatment Plant).	Repeat every third year until both ALs are met for the whole three-year period.
March 31, 2022	For the July through Dec 2021 monitoring, send EGLE certification of Consumer Notice of Lead and Copper results compliance along with a sample copy of the notice delivered.	Download <i>Lead and Copper Report and Consumer Notice of Lead and Copper Results Certificate</i> in Word or PDF format from Michigan.gov/LCR .
June 30, 2022	Deadline for seven percent replacement of lead or GPCL service lines.	Deadline to have replaced a minimum of seven percent of lead or GPCL service lines.
July 1, 2022	Report the 2021 AL exceedance in the CCR.	Specific lead health effects language must be included.
September 28, 2022	For the January through June 2022 monitoring, send EGLE certification of Consumer Notice of Lead and Copper results compliance along with a sample copy of the notice delivered.	Download <i>Lead and Copper Report and Consumer Notice of Lead and Copper Results Certificate</i> in Word or PDF format from Michigan.gov/LCR .
March 31, 2025	Collect one lead and copper sample from each entry point to the distribution system.	Repeat every third year until both ALs are met for the whole three-year period.

Mr. Ellis Mitchell

Page 6

August 3, 2021

We recognize that the Lead and Copper Rule is complex and may be confusing. We will continue to offer assistance in implementing these regulations. If you have any questions, please contact us at BoltJ@Michigan.gov; OnanB@Michigan.gov; or at the phone numbers provided below.

Sincerely,



Jeni Bolt, Environmental Quality Specialist
Lead and Copper Unit
Drinking Water and Environmental
Health Division
517-331-5161



Brandon Onan, Supervisor
Lead and Copper Unit
Drinking Water and Environmental
Health Division
616-307-6736

Enclosures (PA Checklist, PE Distribution Check, WQP report form, Tier Criteria)

cc/enc: Mr. Abul Ahmed, F&V Operations

Mr. Robert Jones, F&V Operations

Ms. Nicki Britten, Berrien County Health Department

Mr. Nick Margaritis, Berrien County Health Department

Mr. Anthony Pavone, Michigan Department of Health and Human Services

Mr. Mike Bolf, EGLE

Mr. Ernie Sarkipato, EGLE

Mr. Matt Sylvester, EGLE

Mr. Ryan VanDerWoude, EGLE



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53687
Work Order: 10402998_28

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	732 MCALISTER, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/21/2021 14:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	04/28/2021 13:50
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/03/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	05/03/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53660
Work Order: 10402998_01

System Name/Owner: BENTON HARBOR
Collection Address: 261 SEARLES, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/21/2021 11:00
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53661
Work Order: 10402998_02

System Name/Owner: BENTON HARBOR
Collection Address: 261 SEARLES, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/21/2021 11:00
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53662
Work Order: 10402998_03

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	718 TERRITORIAL, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/22/2021 10:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	04/28/2021 13:50
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.12	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.021	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53663
Work Order: 10402998_04

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	718 TERRITORIAL, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/22/2021 10:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	04/28/2021 13:50
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.65	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.107	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53664
Work Order: 10402998_05

System Name/Owner: BENTON HARBOR
Collection Address: 663 THRESHER, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/23/2021 13:20
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53665
Work Order: 10402998_06

System Name/Owner: BENTON HARBOR
Collection Address: 663 THRESHER, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/23/2021 13:20
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53666
Work Order: 10402998_07

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	366 MCCORD, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/21/2021 13:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	04/28/2021 13:50
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

Sample Comment LJ53666 Sample did not meet collection volume requirements for test code CCUB when received at the lab. Container was not filled to the base of the neck per sample collection instructions. Result(s) may not be accepted for compliance purposes.

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.006	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53667
Work Order: 10402998_08

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	366 MCCORD, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/21/2021 13:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	04/28/2021 13:50
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

Sample Comment LJ53667 Sample did not meet collection volume requirements for test code CCUB when received at the lab. Container was not filled to the base of the neck per sample collection instructions. Result(s) may not be accepted for compliance purposes.

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.008	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53668
Work Order: 10402998_09

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	534 E MAIN, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/21/2021 11:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	04/28/2021 13:50
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

Sample Comment LJ53668 Sample did not meet collection volume requirements for test code CCUB when received at the lab. Container was not filled to the base of the neck per sample collection instructions. Result(s) may not be accepted for compliance purposes.

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53669
Work Order: 10402998_10

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	534 E MAIN, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/21/2021 11:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	04/28/2021 13:50
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

Sample Comment LJ53669 Sample did not meet collection volume requirements for test code CCUB when received at the lab. Container was not filled to the base of the neck per sample collection instructions. Result(s) may not be accepted for compliance purposes.

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53670
Work Order: 10402998_11

System Name/Owner: BENTON HARBOR
Collection Address: 150 PARKER, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/22/2021 06:00
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.005	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53671
Work Order: 10402998_12

System Name/Owner: BENTON HARBOR
Collection Address: 150 PARKER, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/22/2021 06:00
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report

RECEIVED
May 4 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53672
Work Order: 10402998_13

System Name/Owner: BENTON HARBOR
Collection Address: 807 HIGH, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/22/2021 14:00
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	1.29	mg/L	0.05	05/03/2021	1.3	EPA 200.8	7440-50-8
Lead	0.605	mg/L	0.001	05/03/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53673
Work Order: 10402998_14

System Name/Owner: BENTON HARBOR
Collection Address: 807 HIGH, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/22/2021 14:00
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.69	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.145	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53674
Work Order: 10402998_15

System Name/Owner: BENTON HARBOR
Collection Address: 797 WAUCEDA, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/21/2021 15:00
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53675
Work Order: 10402998_16

System Name/Owner: BENTON HARBOR
Collection Address: 797 WAUCEDA, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/21/2021 15:00
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53676
Work Order: 10402998_17

System Name/Owner: BENTON HARBOR
Collection Address: 127 SEARLES, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/22/2021 08:00
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53677
Work Order: 10402998_18

System Name/Owner: BENTON HARBOR
Collection Address: 127 SEARLES, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/22/2021 08:00
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53678
Work Order: 10402998_19

System Name/Owner: BENTON HARBOR
Collection Address: 754 LAVETTE, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/21/2021 02:30
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53679
Work Order: 10402998_20

System Name/Owner: BENTON HARBOR
Collection Address: 754 LAVETTE, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/21/2021 02:30
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.09	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53680
Work Order: 10402998_21

System Name/Owner: BENTON HARBOR
Collection Address: 711 BUSS, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/21/2021 16:00
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53681
Work Order: 10402998_22

System Name/Owner: BENTON HARBOR
Collection Address: 711 BUSS, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/21/2021 16:00
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53682
Work Order: 10402998_23

System Name/Owner: BENTON HARBOR
Collection Address: 759 BUSS, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/21/2021 06:00
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53683
Work Order: 10402998_24

System Name/Owner: BENTON HARBOR
Collection Address: 759 BUSS,BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/21/2021 06:00
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U .S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53684
Work Order: 10402998_25

System Name/Owner: BENTON HARBOR
Collection Address: 277 HASTINGS, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/22/2021 09:00
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53685
Work Order: 10402998_26

System Name/Owner: BENTON HARBOR
Collection Address: 277 HASTINGS, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/22/2021 09:00
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53686
Work Order: 10402998_27

System Name/Owner: BENTON HARBOR
Collection Address: 732 MCALISTER, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/21/2021 14:00
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53688
Work Order: 10402998_29

System Name/Owner: BENTON HARBOR
Collection Address: 140 BENTON, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/23/2021 10:00
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.11	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53689
Work Order: 10402998_30

System Name/Owner: BENTON HARBOR
Collection Address: 140 BENTON, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/23/2021 10:00
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.20	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53690
Work Order: 10402998_31

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	810 NATE WELLS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/21/2021 17:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	04/28/2021 13:50
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

Sample Comment LJ53690 Sample did not meet collection volume requirements for test code CCUB when received at the lab. Container was not filled to the base of the neck per sample collection instructions. Result(s) may not be accepted for compliance purposes.

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53691
Work Order: 10402998_32

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	810 NATE WELLS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/21/2021 17:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	04/28/2021 13:50
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

Sample Comment LJ53691 Sample did not meet collection volume requirements for test code CCUB when received at the lab. Container was not filled to the base of the neck per sample collection instructions. Result(s) may not be accepted for compliance purposes.

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53692
Work Order: 10402998_33

System Name/Owner: BENTON HARBOR
Collection Address: 753 BROADWAY, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/21/2021 14:00
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53693
Work Order: 10402998_34

System Name/Owner: BENTON HARBOR
Collection Address: 753 BROADWAY, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/21/2021 14:00
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53694
Work Order: 10402998_35

System Name/Owner: BENTON HARBOR
Collection Address: 792 BRITAIN, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/22/2021 11:00
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53695
Work Order: 10402998_36

System Name/Owner: BENTON HARBOR
Collection Address: 792 BRITAIN, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/22/2021 11:00
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53696
Work Order: 10402998_37

System Name/Owner: BENTON HARBOR
Collection Address: 427 FOSTER, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/21/2021 13:24
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ53697
Work Order: 10402998_38

System Name/Owner: BENTON HARBOR
Collection Address: 427 FOSTER, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/21/2021 13:24
Date Received: 04/28/2021 13:50
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: **LJ54648**
Work Order: **10500489_01**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1178 BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/29/2021 09:10
Sample Point:	BATHROOM SINK FIRST DRAW	Date Received:	05/05/2021 12:58
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.022	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: **LJ54649**
Work Order: **10500489_02**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1178 BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/29/2021 09:10
Sample Point:	BATHROOM SINK FIFTH DRAW	Date Received:	05/05/2021 12:58
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.009	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54652
Work Order: 10500489_05

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1237 COLUMBUS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/29/2021 08:30
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/05/2021 12:58
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.023	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54653
Work Order: 10500489_06

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1237 COLUMBUS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/29/2021 08:30
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/05/2021 12:58
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: **LJ54654**
Work Order: **10500489_07**

System Name/Owner: BENTON HARBOR
Collection Address: 857 OGDEN, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: BATHROOM SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/29/2021 07:25
Date Received: 05/05/2021 12:58
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.010	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54655
Work Order: 10500489_08

System Name/Owner: BENTON HARBOR
Collection Address: 857 OGDEN, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: BATHROOM SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/29/2021 07:25
Date Received: 05/05/2021 12:58
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.010	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54656
Work Order: 10500489_09

System Name/Owner: BENTON HARBOR
Collection Address: 849 PIPESTONE, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/30/2021 06:30
Date Received: 05/05/2021 12:58
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.009	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54657
Work Order: 10500489_10

System Name/Owner: BENTON HARBOR
Collection Address: 849 PIPESTONE, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/30/2021 06:30
Date Received: 05/05/2021 12:58
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.008	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54658
Work Order: 10500489_11

System Name/Owner: BENTON HARBOR
Collection Address: 999 PEARL ST, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: BATHROOM SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/28/2021 23:30
Date Received: 05/05/2021 12:58
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.008	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54659
Work Order: 10500489_12

System Name/Owner: BENTON HARBOR
Collection Address: 999 PEARL ST, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: BATHROOM SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/28/2021 23:30
Date Received: 05/05/2021 12:58
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.009	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54660
Work Order: 10500489_13

System Name/Owner: BENTON HARBOR
Collection Address: 931 MONROE, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: BATHROOM SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/29/2021 06:45
Date Received: 05/05/2021 12:58
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.009	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54661
Work Order: 10500489_14

System Name/Owner: BENTON HARBOR
Collection Address: 931 MONROE, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: BATHROOM SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/29/2021 06:45
Date Received: 05/05/2021 12:58
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.014	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54662
Work Order: 10500489_15

System Name/Owner: BENTON HARBOR
Collection Address: 1110 OGDEN, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/27/2021 10:00
Date Received: 05/05/2021 12:58
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54663
Work Order: 10500489_16

System Name/Owner: BENTON HARBOR
Collection Address: 1110 OGDEN, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/27/2021 10:00
Date Received: 05/05/2021 12:58
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54664
Work Order: 10500489_17

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1129 JENNING, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/29/2021 07:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/05/2021 12:58
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.009	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54665
Work Order: 10500489_18

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1129 JENNING, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/29/2021 07:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/05/2021 12:58
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.012	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54666
Work Order: 10500489_19

System Name/Owner: BENTON HARBOR
Collection Address: 1240 PAVONE, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/27/2021 09:00
Date Received: 05/05/2021 12:58
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54667
Work Order: 10500489_20

System Name/Owner: BENTON HARBOR
Collection Address: 1240 PAVONE, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/27/2021 09:00
Date Received: 05/05/2021 12:58
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54668
Work Order: 10500489_21

System Name/Owner: BENTON HARBOR
Collection Address: 270 MAY ST, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/27/2021 08:00
Date Received: 05/05/2021 12:58
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54669
Work Order: 10500489_22

System Name/Owner: BENTON HARBOR
Collection Address: 270 MAY ST, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/27/2021 08:00
Date Received: 05/05/2021 12:58
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54670
Work Order: 10500489_23

System Name/Owner: BENTON HARBOR
Collection Address: 806 LASALLE, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/23/2021 09:00
Date Received: 05/05/2021 12:58
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54671
Work Order: 10500489_24

System Name/Owner: BENTON HARBOR
Collection Address: 806 LASALLE, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/23/2021 09:00
Date Received: 05/05/2021 12:58
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54672
Work Order: 10500489_25

System Name/Owner: BENTON HARBOR
Collection Address: 141 WINAN, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/29/2021 08:15
Date Received: 05/05/2021 12:58
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54673
Work Order: 10500489_26

System Name/Owner: BENTON HARBOR
Collection Address: 141 WINAN, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/29/2021 08:15
Date Received: 05/05/2021 12:58
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54674
Work Order: 10500489_27

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1167 BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/29/2021 06:20
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/05/2021 12:58
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54675
Work Order: 10500489_28

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1167 BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/29/2021 06:20
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/05/2021 12:58
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54676
Work Order: 10500489_29

System Name/Owner: BENTON HARBOR
Collection Address: 1037 PEARL, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/27/2021 13:00
Date Received: 05/05/2021 12:58
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.06	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.005	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54678
Work Order: 10500489_31

System Name/Owner: BENTON HARBOR
Collection Address: 660 MCGUIGAN, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/28/2021 13:06
Date Received: 05/05/2021 12:58
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54679
Work Order: 10500489_32

System Name/Owner: BENTON HARBOR
Collection Address: 660 MCGUIGAN, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/28/2021 13:06
Date Received: 05/05/2021 12:58
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54680
Work Order: 10500489_33

System Name/Owner: BENTON HARBOR
Collection Address: 174 HASTING, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/27/2021 08:00
Date Received: 05/05/2021 12:58
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.013	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54681
Work Order: 10500489_34

System Name/Owner: BENTON HARBOR
Collection Address: 174 HASTING, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/27/2021 08:00
Date Received: 05/05/2021 12:58
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54682
Work Order: 10500489_35

System Name/Owner: BENTON HARBOR
Collection Address: 161 KLINE, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/29/2021 06:45
Date Received: 05/05/2021 12:58
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: **LJ54683**
Work Order: **10500489_36**

System Name/Owner: BENTON HARBOR
Collection Address: 161 KLINE, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/29/2021 06:45
Date Received: 05/05/2021 12:58
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 11 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54650

Work Order: 10500489_03

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	552 BUENA VISTA, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/27/2021 10:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/05/2021 12:58
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	7.65	mg/L	0.05	05/10/2021	1.3	EPA 200.8	7440-50-8
Lead	0.469	mg/L	0.001	05/10/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 11 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54651
Work Order: 10500489_04

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	552 BUENA VISTA, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/27/2021 10:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/05/2021 12:58
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	1.44	mg/L	0.05	05/10/2021	1.3	EPA 200.8	7440-50-8
Lead	0.143	mg/L	0.001	05/10/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED

May 11 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ54677

Work Order: 10500489_30

System Name/Owner: BENTON HARBOR
Collection Address: 1037 PEARL, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 04/27/2021 13:00
Date Received: 05/05/2021 12:58
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	1.30	mg/L	0.05	05/10/2021	1.3	EPA 200.8	7440-50-8
Lead	0.109	mg/L	0.001	05/10/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55761
Work Order: 10501230_01

System Name/Owner: BENTON HARBOR
Collection Address: 582 NILES, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/06/2021 08:00
Date Received: 05/12/2021 14:54
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55762
Work Order: 10501230_02

System Name/Owner: BENTON HARBOR
Collection Address: 582 NILES, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/06/2021 08:00
Date Received: 05/12/2021 14:54
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55763
Work Order: 10501230_03

System Name/Owner: BENTON HARBOR
Collection Address: 1264 PAVONE, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/04/2021 06:40
Date Received: 05/12/2021 14:54
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55764
Work Order: 10501230_04

System Name/Owner: BENTON HARBOR
Collection Address: 1264 PAVONE, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/04/2021 06:40
Date Received: 05/12/2021 14:54
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55765
Work Order: 10501230_05

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	817 NATE WELLS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/06/2021 06:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.11	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.007	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55766
Work Order: 10501230_06

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	817 NATE WELLS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/06/2021 06:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.08	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55767
Work Order: 10501230_07

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1248 BROADWAY BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/07/2021 06:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55768
Work Order: 10501230_08

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1248 BROADWAY BROADWAY, BENTON HARBOR, MI 49022	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/07/2021 06:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55769
Work Order: 10501230_09

System Name/Owner: BENTON HARBOR
Collection Address: 191 SEARLES, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/06/2021 21:30
Date Received: 05/12/2021 14:54
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55770
Work Order: 10501230_10

System Name/Owner: BENTON HARBOR
Collection Address: 191 SEARLES, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/06/2021 21:30
Date Received: 05/12/2021 14:54
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55771
Work Order: 10501230_11

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1086 SUPERIOR, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/05/2021 21:15
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55772
Work Order: 10501230_12

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1086 SUPERIOR, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/05/2021 21:15
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55773
Work Order: 10501230_13

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	626 TERRITORIAL, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/06/2021 10:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.35	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.039	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55774
Work Order: 10501230_14

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	626 TERRITORIAL, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/06/2021 10:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.07	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55775
Work Order: 10501230_15

System Name/Owner: BENTON HARBOR
Collection Address: 558 NILES, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/07/2021 07:00
Date Received: 05/12/2021 14:54
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.05	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55776
Work Order: 10501230_16

System Name/Owner: BENTON HARBOR
Collection Address: 558 NILES, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/07/2021 07:00
Date Received: 05/12/2021 14:54
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.05	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55777
Work Order: 10501230_17

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	717 HIGHLAND, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/06/2021 09:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.13	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.011	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55778
Work Order: 10501230_18

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	717 HIGHLAND, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/06/2021 09:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.12	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.011	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55779
Work Order: 10501230_19

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1111 SUPERIOR, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/06/2021 07:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55780
Work Order: 10501230_20

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1111 SUPERIOR, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/06/2021 07:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55781
Work Order: 10501230_21

System Name/Owner: BENTON HARBOR
Collection Address: 152 LAKE, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/06/2021 11:00
Date Received: 05/12/2021 14:54
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55782
Work Order: 10501230_22

System Name/Owner: BENTON HARBOR
Collection Address: 152 LAKE, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/06/2021 11:00
Date Received: 05/12/2021 14:54
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55783
Work Order: 10501230_23

System Name/Owner: BENTON HARBOR
Collection Address: 208 SEELEY, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/06/2021 09:00
Date Received: 05/12/2021 14:54
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55784
Work Order: 10501230_24

System Name/Owner: BENTON HARBOR
Collection Address: 208 SEELEY, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/06/2021 09:00
Date Received: 05/12/2021 14:54
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55785
Work Order: 10501230_25

System Name/Owner: BENTON HARBOR
Collection Address: 781 BUSS, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/06/2021 06:30
Date Received: 05/12/2021 14:54
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.041	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55786
Work Order: 10501230_26

System Name/Owner: BENTON HARBOR
Collection Address: 781 BUSS, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/06/2021 06:30
Date Received: 05/12/2021 14:54
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55787
Work Order: 10501230_27

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1152 MONROE, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/06/2021 07:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55788
Work Order: 10501230_28

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1152 MONROE, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/06/2021 07:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55789
Work Order: 10501230_29

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1173 LAVETTE, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/06/2021 07:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55790
Work Order: 10501230_30

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1173 LAVETTE, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/06/2021 07:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55791
Work Order: 10501230_31

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1034 BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/06/2021 10:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55792
Work Order: 10501230_32

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1034 BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/06/2021 10:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55793
Work Order: 10501230_33

System Name/Owner: BENTON HARBOR
Collection Address: 823 LAVETTA, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/06/2021 09:41
Date Received: 05/12/2021 14:54
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55794
Work Order: 10501230_34

System Name/Owner: BENTON HARBOR
Collection Address: 823 LAVETTA, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/06/2021 09:41
Date Received: 05/12/2021 14:54
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55795
Work Order: 10501230_35

System Name/Owner: BENTON HARBOR
Collection Address: 166 SEARLES, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: BATHROOM SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/06/2021 11:00
Date Received: 05/12/2021 14:54
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.018	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55796
Work Order: 10501230_36

System Name/Owner: BENTON HARBOR
Collection Address: 166 SEARLES, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: BATHROOM SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/06/2021 11:00
Date Received: 05/12/2021 14:54
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.016	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55798
Work Order: 10501230_38

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	341 BRUNSON, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/07/2021 06:13
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55799
Work Order: 10501230_39

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1046 BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/07/2021 08:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	1.43	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.889	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55800
Work Order: 10501230_40

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1046 BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/07/2021 08:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.08	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.007	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ55797
Work Order: 10501230_37

System Name/Owner: BENTON HARBOR
Collection Address: 341 BRUNSON, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/07/2021 06:13
Date Received: 05/12/2021 14:54
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/19/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/19/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ57925
Work Order: 10502830_01

System Name/Owner: BENTON HARBOR
Collection Address: 596 CASS, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/14/2021 11:00
Date Received: 05/26/2021 15:35
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ57926
Work Order: 10502830_02

System Name/Owner: BENTON HARBOR
Collection Address: 596 CASS, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH STREET
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/14/2021 11:00
Date Received: 05/26/2021 15:35
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ57927
Work Order: 10502830_03

System Name/Owner: BENTON HARBOR
Collection Address: 1008 PEARL, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/18/2021 13:00
Date Received: 05/26/2021 15:35
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ57928
Work Order: 10502830_04

System Name/Owner: BENTON HARBOR
Collection Address: 1008 PEARL, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/18/2021 13:00
Date Received: 05/26/2021 15:35
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ57929
Work Order: 10502830_05

System Name/Owner: BENTON HARBOR
Collection Address: 1274 OGDEN, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/18/2021 14:00
Date Received: 05/26/2021 15:35
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ57930
Work Order: 10502830_06

System Name/Owner: BENTON HARBOR
Collection Address: 1274 OGDEN, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/18/2021 14:00
Date Received: 05/26/2021 15:35
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ57931
Work Order: 10502830_07

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1118 BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/18/2021 19:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/26/2021 15:35
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.006	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ57932
Work Order: 10502830_08

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1118 BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/18/2021 19:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/26/2021 15:35
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.005	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ57933
Work Order: 10502830_09

System Name/Owner: BENTON HARBOR
Collection Address: 507 BRITAIN, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/18/2021 10:00
Date Received: 05/26/2021 15:35
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED
Jun 2 2021
EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ57934
Work Order: 10502830_10

System Name/Owner: BENTON HARBOR
Collection Address: 507 BRITAIN, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/18/2021 10:00
Date Received: 05/26/2021 15:35
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ57935
Work Order: 10502830_11

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	446 PACKARD, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/18/2021 11:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/26/2021 15:35
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ57936
Work Order: 10502830_12

System Name/Owner: BENTON HARBOR
Collection Address: 446 PACKARD, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/18/2021 11:00
Date Received: 05/26/2021 15:35
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ57937
Work Order: 10502830_13

System Name/Owner: BENTON HARBOR
Collection Address: 1037 PEARL, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/18/2021 13:00
Date Received: 05/26/2021 15:35
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ57938
Work Order: 10502830_14

System Name/Owner: BENTON HARBOR
Collection Address: 1037 PEARL, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/18/2021 13:00
Date Received: 05/26/2021 15:35
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

RECEIVED
Jun 2 2021
EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ57939
Work Order: 10502830_15

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1022 HURD, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/18/2021 09:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/26/2021 15:35
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

Sample Comment LJ57939 Sample did not meet collection volume requirements for test code CCUB when received at the lab. Container was not filled to the base of the neck per sample collection instructions. Result(s) may not be accepted for compliance purposes.

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ57940
Work Order: 10502830_16

System Name/Owner: BENTON HARBOR
Collection Address: 1022 HURD, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/18/2021 09:00
Date Received: 05/26/2021 15:35
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: **LJ57941**
Work Order: **10502830_17**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	578 EDWARDS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/18/2021 10:00
Sample Point:	BATHROOM SINK FIRST DRAW	Date Received:	05/26/2021 15:35
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: **LJ57942**
Work Order: **10502830_18**

System Name/Owner: BENTON HARBOR
Collection Address: 578 EDWARDS, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: BATHROOM SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/18/2021 10:00
Date Received: 05/26/2021 15:35
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ57943
Work Order: 10502830_19

System Name/Owner: BENTON HARBOR
Collection Address: 1165 HANNAH, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 05/14/2021 07:31
Date Received: 05/26/2021 15:35
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.06	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ57944
Work Order: 10502830_20

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1165 HANNAH, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/14/2021 07:31
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/26/2021 15:35
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ57945
Work Order: 10502830_21

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1063 COLUMBUS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/18/2021 09:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/26/2021 15:35
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.006	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: **LJ57946**
Work Order: **10502830_22**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1063 COLUMBUS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/18/2021 09:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/26/2021 15:35
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.006	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ57947
Work Order: 10502830_23

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	566 TERRITORIAL, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/17/2021 09:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/26/2021 15:35
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ57948
Work Order: 10502830_24

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	566 TERRITORIAL, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/17/2021 09:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/26/2021 15:35
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ64529
Work Order: 10700001_01

System Name/Owner: BENTON HARBOR
Collection Address: 204 GARFIELD, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: BATHROOM SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 06/22/2021 10:00
Date Received: 07/01/2021 07:55
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ64530
Work Order: 10700001_02

System Name/Owner: BENTON HARBOR
Collection Address: 204 GARFIELD, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: BATHROOM SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code:
Collector: Other
Date Collected: 06/22/2021 10:00
Date Received: 07/01/2021 07:55
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ64531
Work Order: 10700001_03

System Name/Owner: BENTON HARBOR
Collection Address: 1066 MONROE, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: BATHROOM SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 06/22/2021 10:00
Date Received: 07/01/2021 07:55
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ64532
Work Order: 10700001_04

System Name/Owner: BENTON HARBOR
Collection Address: 1066 MONROE, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: BATHROOM SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 06/22/2021 10:00
Date Received: 07/01/2021 07:55
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ64533
Work Order: 10700001_05

System Name/Owner: BENTON HARBOR
Collection Address: 285 HASTING, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 06/24/2021 06:30
Date Received: 07/01/2021 07:55
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ64534
Work Order: 10700001_06

System Name/Owner: BENTON HARBOR
Collection Address: 285 HASTING, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 06/24/2021 06:30
Date Received: 07/01/2021 07:55
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ64535
Work Order: 10700001_07

System Name/Owner: BENTON HARBOR
Collection Address: 823 LAVETTE, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code:
Collector: Other
Date Collected: 06/23/2021 06:00
Date Received: 07/01/2021 07:55
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ64536
Work Order: 10700001_08

System Name/Owner: BENTON HARBOR
Collection Address: 823 LAVETTE, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 06/23/2021 06:00
Date Received: 07/01/2021 07:55
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ64537
Work Order: 10700001_09

System Name/Owner: BENTON HARBOR
Collection Address: 1043 AGARD, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: BATHROOM SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 06/22/2021 09:00
Date Received: 07/01/2021 07:55
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ64538
Work Order: 10700001_10

System Name/Owner: BENTON HARBOR
Collection Address: 1043 AGARD, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: BATHROOM SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 06/22/2021 09:00
Date Received: 07/01/2021 07:55
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.009	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ64539
Work Order: 10700001_11

System Name/Owner: BENTON HARBOR
Collection Address: 1225 COLFAX, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 06/22/2021 06:00
Date Received: 07/01/2021 07:55
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ64540
Work Order: 10700001_12

System Name/Owner: BENTON HARBOR
Collection Address: 1225 COLFAX, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 06/22/2021 06:00
Date Received: 07/01/2021 07:55
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ64541
Work Order: 10700001_13

System Name/Owner: BENTON HARBOR
Collection Address: 1143 UNION, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 06/22/2021 06:25
Date Received: 07/01/2021 07:55
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ64542
Work Order: 10700001_14

System Name/Owner: BENTON HARBOR
Collection Address: 1143 UNION, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 06/22/2021 06:25
Date Received: 07/01/2021 07:55
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ64543
Work Order: 10700001_15

System Name/Owner: BENTON HARBOR
Collection Address: 201 GARFIELD, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 06/22/2021 09:00
Date Received: 07/01/2021 07:55
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.006	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ64544
Work Order: 10700001_16

System Name/Owner: BENTON HARBOR
Collection Address: 201 GARFIELD, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 06/22/2021 09:00
Date Received: 07/01/2021 07:55
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.014	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ64545
Work Order: 10700001_17

System Name/Owner: BENTON HARBOR
Collection Address: 1161 UNION, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 06/22/2021 12:00
Date Received: 07/01/2021 07:55
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.007	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ64546
Work Order: 10700001_18

System Name/Owner: BENTON HARBOR
Collection Address: 1161 UNION, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 06/22/2021 12:00
Date Received: 07/01/2021 07:55
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.007	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ64547
Work Order: 10700001_19

System Name/Owner: BENTON HARBOR
Collection Address: 1191 PAVONE, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: BATHROOM SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 06/22/2021 18:00
Date Received: 07/01/2021 07:55
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ64548
Work Order: 10700001_20

System Name/Owner: BENTON HARBOR
Collection Address: 1191 PAVONE, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: BATHROOM SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 06/22/2021 18:00
Date Received: 07/01/2021 07:55
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ64549
Work Order: 10700001_21

System Name/Owner: BENTON HARBOR
Collection Address: 1020 BISHOP, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 06/22/2021 10:00
Date Received: 07/01/2021 07:55
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ64550
Work Order: 10700001_22

System Name/Owner: BENTON HARBOR
Collection Address: 1020 BISHOP, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH SINK
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 06/22/2021 10:00
Date Received: 07/01/2021 07:55
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ64551
Work Order: 10700001_23

System Name/Owner: BENTON HARBOR
Collection Address: 946 BISHOP, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 06/22/2021 07:00
Date Received: 07/01/2021 07:55
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ64552
Work Order: 10700001_24

System Name/Owner: BENTON HARBOR
Collection Address: 946 BISHOP, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 06/22/2021 07:00
Date Received: 07/01/2021 07:55
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ64553
Work Order: 10700001_25

System Name/Owner: BENTON HARBOR
Collection Address: 768 BROADWAY, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 06/24/2021 08:00
Date Received: 07/01/2021 07:55
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ64554
Work Order: 10700001_26

System Name/Owner: BENTON HARBOR
Collection Address: 768 BROADWAY, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 06/24/2021 08:00
Date Received: 07/01/2021 07:55
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ64555
Work Order: 10700001_27

System Name/Owner: BENTON HARBOR
Collection Address: 1112 AGARD, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIRST DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 06/22/2021 22:00
Date Received: 07/01/2021 07:55
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.028	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES
601 N RIDGEWAY CT
ST JOSEPH MI 49085

Sample ID: LJ64556
Work Order: 10700001_28

System Name/Owner: BENTON HARBOR
Collection Address: 1112 AGARD, BENTON HARBOR
Collected By: RESIDENT
Township/Well#/Section: //
County: Berrien
Sample Point: KITCHEN SINK FIFTH DRAW
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600
Source: TYPE I
Site Code: DIST
Collector: Other
Date Collected: 06/22/2021 22:00
Date Received: 07/01/2021 07:55
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

**Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623**

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report

RECEIVED
Mar 9 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
1275 HILLTOP RD
ST JOSEPH MI 49022

Sample ID: LJ46050
Work Order: 10300174_01

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	246 PIPESTONE, BENTON HARBOR	Source:	TYPE I
Collected By:	RICE	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	03/01/2021 17:30
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	03/02/2021 13:19
Water System:	Treated Public Distribution System	Purpose:	Other

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	03/03/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	03/03/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane

Official Laboratory Report

RECEIVED
Mar 9 2021
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES
1275 HILLTOP RD
ST JOSEPH MI 49022

Sample ID: LJ46051
Work Order: 10300174_02

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	246 PIPESTONE, BENTON HARBOR	Source:	TYPE I
Collected By:	RICE	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	03/01/2021 17:30
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	03/02/2021 13:19
Water System:	Treated Public Distribution System	Purpose:	Other

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	03/03/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	03/03/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.

Berrien County
2149 E. Napier Ave.
Benton Harbor, MI 49022
269 927-5623

RL: Reporting Limit
MCL: Maximum Contaminant Level
AL: Action Level
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)
ng/L: nanograms / Liter (ppt)
MPN: Most Probable Number

CFU: Colony Forming Unit
CAS: Chemical Abstract Service
Laboratory Contact: Marlene Kane