

## WSSN 0600 City of Benton Harbor 1st Half 2021

Lead and Copper Report and Consumer Notice for Community Water Supply Form A -Supplies with Lead Service Leads												
Sample Location	Sample Date	Tier (1,2, 3, OT)	Category	Building Plumbing	Service Line (L, C, G, P)	Tap Type (K, B)	1st Draw			5th Draw		
							Lead ppb	Sample ID	Copper ppb	Lead ppb	Sample ID	Copper ppb
261 Searles	04/21/21	1	A		L	K	ND	LJ53660	ND	ND	LJ53661	ND
718 Territorial	04/22/21	1	A		L	K	21	LJ53662	120	107	LJ53663	650
663 Thresher	04/23/21	1	A		L	K	1	LJ53664	ND	ND	LJ53665	ND
150 Parker	04/22/21	1	A		L	K	5	LJ53670	ND	2	LJ53671	ND
797 Wauceda	04/21/21	1	A		L	K	4	LJ53674	ND	3	LJ53675	ND
127 Searles	04/22/21	1	A		L	K	2	LJ53676	ND	3	LJ53677	ND
754 Lavette	04/21/21	1	A		L	K	2	LJ53678	ND	ND	LJ53679	90
711 Buss	04/21/21	1	A		L	K	ND	LJ53680	ND	ND	LJ53681	ND
759 Buss	04/21/21	1	A		L	K	3	LJ53682	ND	1	LJ53683	ND
277 Hastings	04/22/21	1	A		L	K	2	LJ53684	ND	3	LJ53685	ND
732 McAlister	04/21/21	1	A		L	K	1	LJ53686	ND	2	LJ53687	ND
140 Benton	04/23/21	1	A		L	K	ND	LJ53688	110	ND	LJ53689	200
753 Broadway	04/21/21	1	A		L	K	ND	LJ53692	ND	1	LJ53693	ND
792 Britain	04/22/21	1	A		L	K	1	LJ53694	ND	ND	LJ53695	ND
1178 Broadway	04/29/21	1	A		L	K	22	LJ54648	ND	9	LJ54649	ND
1237 Columbus	04/29/21	1	A		L	K	23	LJ54652	ND	4	LJ54653	ND
857 Ogden	04/29/21	1	A		L	B	10	LJ54654	ND	10	LJ54655	ND
999 Pearl	04/28/21	1	A		L	B	8	LJ54658	ND	9	LJ54659	ND
931 Monroe	04/29/21	1	A		L	B	9	LJ54660	ND	14	LJ54661	ND
1110 Ogden	04/27/21	1	A		L	K	ND	LJ54662	ND	3	LJ54663	ND
1129 Jennings	04/29/21	1	A		L	K	9	LJ54664	ND	12	LJ54665	ND
806 Lasalle	04/23/21	1	A		L	K	ND	LJ54670	ND	ND	LJ54671	ND
141 Winan	04/29/21	1	A		L	K	ND	LJ54672	ND	ND	LJ54673	ND
1167 Broadway	04/29/21	1	A		L	K	1	LJ54674	ND	ND	LJ54675	ND
660 McGuigan	04/28/21	1	A		L	K	ND	LJ54678	ND	ND	LJ54679	ND
174 Hasting	04/27/21	1	A		L	K	13	LJ54680	ND	2	LJ54681	ND
161 Kline	04/29/21	1	A		L	K	4	LJ54682	ND	ND	LJ54682	ND
552 Buena Vista	04/27/21	1	A		L	K	469	LJ54650	7650	143	LJ54651	1440
582 Niles	05/06/21	1	A		L	K	2	LJ55761	ND	2	LJ55762	ND

1264 Pavone	05/04/21	1	A		L	K	2	LJ55763	ND	ND	LJ55764	ND
817 Nate Wells	05/06/21	1	A		L	K	7	LJ55765	110	3	LJ55766	80
1248 Broadway	05/07/21	1	A		L	K	2	LJ55767	ND	2	LJ55768	ND
191 Searles	05/06/21	1	A		L	K	ND	LJ55769	ND	ND	LJ55770	ND
1086 Superior	05/05/21	1	A		L	K	ND	LJ55771	ND	ND	LJ55772	ND
208 Seeley	05/06/21	1	A		L	K	ND	LJ55783	ND	ND	LJ55784	ND
781 Buss	05/06/21	1	A		L	K	41	LJ55785	ND	4	LJ55786	ND
166 Searles	05/06/21	1	A		L	K	18	LJ55795	ND	16	LJ55796	ND
341 Brunson	05/07/21	1	A		L	K	ND	LJ55797	ND	ND	LJ55798	ND
596 Cass	05/14/21	1	A		L	K	ND	LJ57925	ND	ND	LJ57926	ND
1274 Ogden	05/18/21	1	A		L	K	ND	LJ57929	ND	ND	LJ57930	ND
1118 Broadway	05/18/21	1	A		L	K	6	LJ57931	ND	5	LJ57932	ND
446 Packard	05/18/21	1	A		L	K	1	LJ57935	ND	ND	LJ57936	ND
578 Edwards	05/18/21	1	A		L	B	ND	LJ57941	ND	ND	LJ57942	ND
1165 Hannah	05/14/21	1	A		L	K	2	LJ57943	60	1	LJ57944	ND
566 Territorial	05/17/21	1	A		L	K	1	LJ57947	ND	1	LJ57948	ND
1037 Pearl	05/18/21	1	A		L	K	1	LJ57937	ND	1	LJ57938	ND
1037 Pearl	04/27/21	1	A	duplicate	L	K	5	LJ54676	60	109	LJ54677	1300
366 McCord	04/21/21	1	A	volume<	L	K	6	LJ53666	ND	8	LJ53667	ND
534 E Main	04/21/21	1	A	volume<	L	K	ND	LJ53668	ND	ND	LJ53669	ND
1022 Hurd	05/18/21	1	A	volume<	L	K	ND	LJ57939	ND	ND	LJ57940	ND
810 Nate Wells	04/21/21	1	A	volume<	L	K	ND	LJ53690	ND	ND	LJ53691	ND
946 BISHOP	06/22/21	1	A		L	K	2	LJ64551	ND	1	LJ64552	ND
285 Hastings	06/24/21	1	A		L	K	1	LJ64533	ND	1	LJ64534	ND
1112 Agard	06/22/21	1	A		L	K	28	LJ64555	ND	2	LJ64556	ND
1020 Bishop	06/22/21	1	A		L	K	ND	LJ64549	ND	ND	LJ64550	ND
768 Broadway	06/24/21	1	A		L	K	ND	LJ64553	ND	ND	LJ64554	ND
1191 Pavone	06/22/21	1	A		L	B	ND	LJ64547	ND	2	LJ64548	ND
1225 Colfax	06/22/21	1	A		L	K	3	LJ64539	ND	2	LJ64540	ND
1161 Union St	06/22/21	1	A		L	K	7	LJ64545	ND	7	LJ64546	ND
1143 Union	06/22/21	1	A		L	K	ND	LJ64541	ND	ND	LJ64542	ND
201 Garfield	06/22/21	1	A		L	K	6	LJ64543	ND	14	LJ64544	ND
204 Garfield	06/22/21	1	A		L	B	ND	LJ64529	ND	ND	LJ64530	ND
1043 Agard	06/22/21	1	A		L	B	3	LJ64537	ND	9	LJ64538	ND
1066 Monroe	06/22/21	1	A		L	B	ND	LJ64531	ND	4	LJ64532	ND
1008 Pearl	05/18/21	1	A		L	K	ND	LJ57927	ND	ND	LJ57928	ND
807 High	04/22/21	1	A		L	K	605	LJ53672	1290	145	LJ53673	690
246 Pipestone	03/01/21	2	D		L	K	ND	LJ46050	ND	ND	LJ46051	ND
427 Foster	04/21/21	unknown				K	ND	LJ53696	ND	ND	LJ53697	ND
849 Pipestone	04/30/21	unknown				K	9	LJ54656	ND	8	LJ54657	ND
1240 Pavone	04/27/21	unknown				K	ND	LJ54666	ND	ND	LJ54667	ND
270 May	04/27/21	unknown				K	4	LJ54668	ND	ND	LJ54669	ND

626 Territorial	05/06/21	unknown				K	39	LJ55773	350	4	LJ55774	70
558 Niles	05/07/21	unknown				K	2	LJ55775	50	2	LJ55776	50
717 Highland	05/06/21	unknown				K	11	LJ55777	130	11	LJ55778	120
1111 Superior	05/06/21	unknown				K	ND	LJ55779	ND	ND	LJ55780	ND
152 Lake	05/06/21	unknown				K	ND	LJ55781	ND	ND	LJ55782	ND
1152 Monroe	05/06/21	unknown				K	1	LJ55787	ND	ND	LJ55788	ND
1173 Lavette	05/06/21	unknown				K	1	LJ55789	ND	4	LJ55790	ND
1034 Broadway	05/06/21	unknown				K	ND	LJ55791	ND	ND	LJ55792	ND
823 Lavette	05/06/21	unknown				K	ND	LJ55793	ND	ND	LJ55794	ND
1046 Broadway	05/07/21	unknown				K	889	LJ55799	1433	7	LJ55800	80
507 Britain	05/18/21	unknown				K	ND	LJ57933	ND	ND	LJ57934	ND
1063 Columbus	05/18/21	unknown				K	6	LJ57945	ND	6	LJ57946	ND
823 Lavette	06/23/21	unknown				K	ND	LJ64535	ND	ND	LJ64536	ND

Official Laboratory Report

**RECEIVED**  
Mar 9 2021  
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES  
1275 HILLTOP RD  
ST JOSEPH MI 49022

**Sample ID: LJ46050**  
**Work Order: 10300174\_01**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	246 PIPESTONE, BENTON HARBOR	Source:	TYPE I
Collected By:	RICE	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	03/01/2021 17:30
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	03/02/2021 13:19
Water System:	Treated Public Distribution System	Purpose:	Other

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	03/03/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	03/03/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



Official Laboratory Report

**RECEIVED**  
Mar 9 2021  
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES  
1275 HILLTOP RD  
ST JOSEPH MI 49022

Sample ID: LJ46051  
Work Order: 10300174\_02

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	246 PIPESTONE, BENTON HARBOR	Source:	TYPE I
Collected By:	RICE	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	03/01/2021 17:30
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	03/02/2021 13:19
Water System:	Treated Public Distribution System	Purpose:	Other

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	03/03/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	03/03/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

## Official Laboratory Report



Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ64529**  
**Work Order: 10700001\_01**

System Name/Owner: BENTON HARBOR  
Collection Address: 204 GARFIELD, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: BATHROOM SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 06/22/2021 10:00  
Date Received: 07/01/2021 07:55  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

## Official Laboratory Report



Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ64530  
Work Order: 10700001\_02

System Name/Owner: BENTON HARBOR  
Collection Address: 204 GARFIELD, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: BATHROOM SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code:  
Collector: Other  
Date Collected: 06/22/2021 10:00  
Date Received: 07/01/2021 07:55  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

## Official Laboratory Report



Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ64531  
Work Order: 10700001\_03

System Name/Owner: BENTON HARBOR  
Collection Address: 1066 MONROE, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: BATHROOM SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 06/22/2021 10:00  
Date Received: 07/01/2021 07:55  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

## Official Laboratory Report



Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ64532**  
**Work Order: 10700001\_04**

System Name/Owner: BENTON HARBOR  
Collection Address: 1066 MONROE, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: BATHROOM SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 06/22/2021 10:00  
Date Received: 07/01/2021 07:55  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

## Official Laboratory Report



Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ64533**  
**Work Order: 10700001\_05**

System Name/Owner: BENTON HARBOR  
Collection Address: 285 HASTING, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 06/24/2021 06:30  
Date Received: 07/01/2021 07:55  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ64534**  
**Work Order: 10700001\_06**

System Name/Owner: BENTON HARBOR  
Collection Address: 285 HASTING, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 06/24/2021 06:30  
Date Received: 07/01/2021 07:55  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

## Official Laboratory Report



Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ64535  
Work Order: 10700001\_07

System Name/Owner: BENTON HARBOR  
Collection Address: 823 LAVETTE, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code:  
Collector: Other  
Date Collected: 06/23/2021 06:00  
Date Received: 07/01/2021 07:55  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



Official Laboratory Report



Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ64536**  
**Work Order: 10700001\_08**

System Name/Owner: BENTON HARBOR  
Collection Address: 823 LAVETTE, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 06/23/2021 06:00  
Date Received: 07/01/2021 07:55  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ64537**  
**Work Order: 10700001\_09**

System Name/Owner: BENTON HARBOR  
Collection Address: 1043 AGARD, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: BATHROOM SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 06/22/2021 09:00  
Date Received: 07/01/2021 07:55  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ64538**  
**Work Order: 10700001\_10**

System Name/Owner: BENTON HARBOR  
Collection Address: 1043 AGARD, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: BATHROOM SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 06/22/2021 09:00  
Date Received: 07/01/2021 07:55  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.009	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ64539**  
**Work Order: 10700001\_11**

System Name/Owner: BENTON HARBOR  
Collection Address: 1225 COLFAX, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 06/22/2021 06:00  
Date Received: 07/01/2021 07:55  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

## Official Laboratory Report



Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ64540  
Work Order: 10700001\_12

System Name/Owner: BENTON HARBOR  
Collection Address: 1225 COLFAX, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 06/22/2021 06:00  
Date Received: 07/01/2021 07:55  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

## Official Laboratory Report



Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ64541  
Work Order: 10700001\_13

System Name/Owner: BENTON HARBOR  
Collection Address: 1143 UNION, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 06/22/2021 06:25  
Date Received: 07/01/2021 07:55  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ64542  
Work Order: 10700001\_14

System Name/Owner: BENTON HARBOR  
Collection Address: 1143 UNION, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 06/22/2021 06:25  
Date Received: 07/01/2021 07:55  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

Official Laboratory Report



Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ64543**  
**Work Order: 10700001\_15**

System Name/Owner: BENTON HARBOR  
Collection Address: 201 GARFIELD, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 06/22/2021 09:00  
Date Received: 07/01/2021 07:55  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.006	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report



Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ64544  
Work Order: 10700001\_16

System Name/Owner: BENTON HARBOR  
Collection Address: 201 GARFIELD, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 06/22/2021 09:00  
Date Received: 07/01/2021 07:55  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.014	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

## Official Laboratory Report



Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ64545  
Work Order: 10700001\_17

System Name/Owner: BENTON HARBOR  
Collection Address: 1161 UNION, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 06/22/2021 12:00  
Date Received: 07/01/2021 07:55  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.007	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

## Official Laboratory Report



Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ64546  
Work Order: 10700001\_18

System Name/Owner: BENTON HARBOR  
Collection Address: 1161 UNION, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 06/22/2021 12:00  
Date Received: 07/01/2021 07:55  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.007	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

## Official Laboratory Report



Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ64547  
Work Order: 10700001\_19

System Name/Owner: BENTON HARBOR  
Collection Address: 1191 PAVONE, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: BATHROOM SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 06/22/2021 18:00  
Date Received: 07/01/2021 07:55  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

## Official Laboratory Report



Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ64548  
Work Order: 10700001\_20

System Name/Owner: BENTON HARBOR  
Collection Address: 1191 PAVONE, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: BATHROOM SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 06/22/2021 18:00  
Date Received: 07/01/2021 07:55  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

## Official Laboratory Report



Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ64549  
Work Order: 10700001\_21

System Name/Owner: BENTON HARBOR  
Collection Address: 1020 BISHOP, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 06/22/2021 10:00  
Date Received: 07/01/2021 07:55  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

## Official Laboratory Report



Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ64550  
Work Order: 10700001\_22

System Name/Owner: BENTON HARBOR  
Collection Address: 1020 BISHOP, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH SINK  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 06/22/2021 10:00  
Date Received: 07/01/2021 07:55  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

## Official Laboratory Report



Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ64551  
Work Order: 10700001\_23

System Name/Owner: BENTON HARBOR  
Collection Address: 946 BISHOP, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 06/22/2021 07:00  
Date Received: 07/01/2021 07:55  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



Official Laboratory Report



Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ64552**  
**Work Order: 10700001\_24**

System Name/Owner: BENTON HARBOR  
Collection Address: 946 BISHOP, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 06/22/2021 07:00  
Date Received: 07/01/2021 07:55  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

## Official Laboratory Report



Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ64553**  
**Work Order: 10700001\_25**

System Name/Owner: BENTON HARBOR  
Collection Address: 768 BROADWAY, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 06/24/2021 08:00  
Date Received: 07/01/2021 07:55  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

## Official Laboratory Report



Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ64554  
Work Order: 10700001\_26

System Name/Owner: BENTON HARBOR  
Collection Address: 768 BROADWAY, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 06/24/2021 08:00  
Date Received: 07/01/2021 07:55  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

## Official Laboratory Report



Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ64555  
Work Order: 10700001\_27

System Name/Owner: BENTON HARBOR  
Collection Address: 1112 AGARD, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 06/22/2021 22:00  
Date Received: 07/01/2021 07:55  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.028	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

## Official Laboratory Report



Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ64556  
Work Order: 10700001\_28

System Name/Owner: BENTON HARBOR  
Collection Address: 1112 AGARD, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 06/22/2021 22:00  
Date Received: 07/01/2021 07:55  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	07/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	07/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ57925**  
**Work Order: 10502830\_01**

System Name/Owner: BENTON HARBOR  
Collection Address: 596 CASS, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/14/2021 11:00  
Date Received: 05/26/2021 15:35  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ57926**  
**Work Order: 10502830\_02**

System Name/Owner: BENTON HARBOR  
Collection Address: 596 CASS, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH STREET  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/14/2021 11:00  
Date Received: 05/26/2021 15:35  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ57927  
Work Order: 10502830\_03

System Name/Owner: BENTON HARBOR  
Collection Address: 1008 PEARL, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/18/2021 13:00  
Date Received: 05/26/2021 15:35  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane





## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: **LJ57928**  
Work Order: **10502830\_04**

System Name/Owner: BENTON HARBOR  
Collection Address: 1008 PEARL, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/18/2021 13:00  
Date Received: 05/26/2021 15:35  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ57929  
Work Order: 10502830\_05

System Name/Owner: BENTON HARBOR  
Collection Address: 1274 OGDEN, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/18/2021 14:00  
Date Received: 05/26/2021 15:35  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ57930**  
**Work Order: 10502830\_06**

System Name/Owner: BENTON HARBOR  
Collection Address: 1274 OGDEN, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/18/2021 14:00  
Date Received: 05/26/2021 15:35  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ57931  
Work Order: 10502830\_07

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1118 BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/18/2021 19:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/26/2021 15:35
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.006	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ57932  
Work Order: 10502830\_08

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1118 BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/18/2021 19:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/26/2021 15:35
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.005	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ57933**  
**Work Order: 10502830\_09**

System Name/Owner: BENTON HARBOR  
Collection Address: 507 BRITAIN, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/18/2021 10:00  
Date Received: 05/26/2021 15:35  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ57934  
Work Order: 10502830\_10

System Name/Owner: BENTON HARBOR  
Collection Address: 507 BRITAIN, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/18/2021 10:00  
Date Received: 05/26/2021 15:35  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ57935  
Work Order: 10502830\_11

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	446 PACKARD, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/18/2021 11:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/26/2021 15:35
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane





## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ57936**  
**Work Order: 10502830\_12**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	446 PACKARD, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/18/2021 11:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/26/2021 15:35
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ57937**  
**Work Order: 10502830\_13**

System Name/Owner: BENTON HARBOR  
Collection Address: 1037 PEARL, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/18/2021 13:00  
Date Received: 05/26/2021 15:35  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**  
Jun 2 2021  
EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ57938**  
**Work Order: 10502830\_14**

System Name/Owner: BENTON HARBOR  
Collection Address: 1037 PEARL, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/18/2021 13:00  
Date Received: 05/26/2021 15:35  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**  
Jun 2 2021  
EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ57939**  
**Work Order: 10502830\_15**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1022 HURD, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/18/2021 09:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/26/2021 15:35
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

**Sample Comment LJ57939** Sample did not meet collection volume requirements for test code CCUB when received at the lab. Container was not filled to the base of the neck per sample collection instructions. Result(s) may not be accepted for compliance purposes.

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ57940**  
**Work Order: 10502830\_16**

System Name/Owner: BENTON HARBOR  
Collection Address: 1022 HURD, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/18/2021 09:00  
Date Received: 05/26/2021 15:35  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ57941**  
**Work Order: 10502830\_17**

System Name/Owner: BENTON HARBOR  
Collection Address: 578 EDWARDS, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: BATHROOM SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/18/2021 10:00  
Date Received: 05/26/2021 15:35  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**  
Jun 2 2021  
EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ57942**  
**Work Order: 10502830\_18**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	578 EDWARDS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/18/2021 10:00
Sample Point:	BATHROOM SINK FIFTH DRAW	Date Received:	05/26/2021 15:35
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ57943**  
**Work Order: 10502830\_19**

System Name/Owner: BENTON HARBOR  
Collection Address: 1165 HANNAH, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/14/2021 07:31  
Date Received: 05/26/2021 15:35  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.06	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane





## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: **LJ57944**  
Work Order: **10502830\_20**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1165 HANNAH, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/14/2021 07:31
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/26/2021 15:35
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ57945**  
**Work Order: 10502830\_21**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1063 COLUMBUS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/18/2021 09:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/26/2021 15:35
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.006	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ57946  
Work Order: 10502830\_22

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1063 COLUMBUS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/18/2021 09:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/26/2021 15:35
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.006	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ57947**  
**Work Order: 10502830\_23**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	566 TERRITORIAL, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/17/2021 09:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/26/2021 15:35
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ57948**  
**Work Order: 10502830\_24**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	566 TERRITORIAL, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/17/2021 09:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/26/2021 15:35
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/27/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	05/27/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ55797  
Work Order: 10501230\_37

System Name/Owner: BENTON HARBOR  
Collection Address: 341 BRUNSON, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/07/2021 06:13  
Date Received: 05/12/2021 14:54  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/19/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/19/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55761**  
**Work Order: 10501230\_01**

System Name/Owner: BENTON HARBOR  
Collection Address: 582 NILES, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/06/2021 08:00  
Date Received: 05/12/2021 14:54  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55762**  
**Work Order: 10501230\_02**

System Name/Owner: BENTON HARBOR  
Collection Address: 582 NILES, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/06/2021 08:00  
Date Received: 05/12/2021 14:54  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane





Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55763**  
**Work Order: 10501230\_03**

System Name/Owner: BENTON HARBOR  
Collection Address: 1264 PAVONE, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/04/2021 06:40  
Date Received: 05/12/2021 14:54  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55764**  
**Work Order: 10501230\_04**

System Name/Owner: BENTON HARBOR  
Collection Address: 1264 PAVONE, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/04/2021 06:40  
Date Received: 05/12/2021 14:54  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55765**  
**Work Order: 10501230\_05**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	817 NATE WELLS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/06/2021 06:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.11	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.007	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55766**  
**Work Order: 10501230\_06**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	817 NATE WELLS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/06/2021 06:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.08	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55767**  
**Work Order: 10501230\_07**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1248 BROADWAY BROADWAY, BENTON HARBOR, MI 49022	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/07/2021 06:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55768**  
**Work Order: 10501230\_08**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1248 BROADWAY BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/07/2021 06:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55769**  
**Work Order: 10501230\_09**

System Name/Owner: BENTON HARBOR  
Collection Address: 191 SEARLES, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/06/2021 21:30  
Date Received: 05/12/2021 14:54  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55770**  
**Work Order: 10501230\_10**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	191 SEARLES, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/06/2021 21:30
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane





## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55771**  
**Work Order: 10501230\_11**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1086 SUPERIOR, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/05/2021 21:15
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55772**  
**Work Order: 10501230\_12**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1086 SUPERIOR, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/05/2021 21:15
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55773**  
**Work Order: 10501230\_13**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	626 TERRITORIAL, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/06/2021 10:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.35	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.039	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55774**  
**Work Order: 10501230\_14**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	626 TERRITORIAL,BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/06/2021 10:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.07	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U .S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55775**  
**Work Order: 10501230\_15**

System Name/Owner: BENTON HARBOR  
Collection Address: 558 NILES, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/07/2021 07:00  
Date Received: 05/12/2021 14:54  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.05	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55776**  
**Work Order: 10501230\_16**

System Name/Owner: BENTON HARBOR  
Collection Address: 558 NILES, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/07/2021 07:00  
Date Received: 05/12/2021 14:54  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.05	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55777**  
**Work Order: 10501230\_17**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	717 HIGHLAND, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/06/2021 09:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.13	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.011	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55778**  
**Work Order: 10501230\_18**

System Name/Owner: BENTON HARBOR  
Collection Address: 717 HIGHLAND, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/06/2021 09:00  
Date Received: 05/12/2021 14:54  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.12	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.011	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane





## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55779**  
**Work Order: 10501230\_19**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1111 SUPERIOR, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/06/2021 07:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55780**  
**Work Order: 10501230\_20**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1111 SUPERIOR, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/06/2021 07:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55781**  
**Work Order: 10501230\_21**

System Name/Owner: BENTON HARBOR  
Collection Address: 152 LAKE, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/06/2021 11:00  
Date Received: 05/12/2021 14:54  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55782**  
**Work Order: 10501230\_22**

System Name/Owner: BENTON HARBOR  
Collection Address: 152 LAKE, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/06/2021 11:00  
Date Received: 05/12/2021 14:54  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55783**  
**Work Order: 10501230\_23**

System Name/Owner: BENTON HARBOR  
Collection Address: 208 SEELEY, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/06/2021 09:00  
Date Received: 05/12/2021 14:54  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55784**  
**Work Order: 10501230\_24**

System Name/Owner: BENTON HARBOR  
Collection Address: 208 SEELEY, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/06/2021 09:00  
Date Received: 05/12/2021 14:54  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55785**  
**Work Order: 10501230\_25**

System Name/Owner: BENTON HARBOR  
Collection Address: 781 BUSS,BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/06/2021 06:30  
Date Received: 05/12/2021 14:54  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.041	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U .S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55786**  
**Work Order: 10501230\_26**

System Name/Owner: BENTON HARBOR  
Collection Address: 781 BUSS, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/06/2021 06:30  
Date Received: 05/12/2021 14:54  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane





## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55787**  
**Work Order: 10501230\_27**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1152 MONROE, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/06/2021 07:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55788**  
**Work Order: 10501230\_28**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1152 MONROE, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/06/2021 07:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55789**  
**Work Order: 10501230\_29**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1173 LAVETTE, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/06/2021 07:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55790**  
**Work Order: 10501230\_30**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1173 LAVETTE, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/06/2021 07:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55791**  
**Work Order: 10501230\_31**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1034 BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/06/2021 10:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55792**  
**Work Order: 10501230\_32**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1034 BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/06/2021 10:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55793**  
**Work Order: 10501230\_33**

System Name/Owner: BENTON HARBOR  
Collection Address: 823 LAVETTA, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/06/2021 09:41  
Date Received: 05/12/2021 14:54  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55794**  
**Work Order: 10501230\_34**

System Name/Owner: BENTON HARBOR  
Collection Address: 823 LAVETTA, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/06/2021 09:41  
Date Received: 05/12/2021 14:54  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane





## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55795**  
**Work Order: 10501230\_35**

System Name/Owner: BENTON HARBOR  
Collection Address: 166 SEARLES, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: BATHROOM SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/06/2021 11:00  
Date Received: 05/12/2021 14:54  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.018	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55796**  
**Work Order: 10501230\_36**

System Name/Owner: BENTON HARBOR  
Collection Address: 166 SEARLES, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: BATHROOM SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 05/06/2021 11:00  
Date Received: 05/12/2021 14:54  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.016	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55798**  
**Work Order: 10501230\_38**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	341 BRUNSON, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/07/2021 06:13
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55799**  
**Work Order: 10501230\_39**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1046 BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/07/2021 08:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	1.43	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.889	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ55800**  
**Work Order: 10501230\_40**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1046 BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	05/07/2021 08:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/12/2021 14:54
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.08	mg/L	0.05	05/14/2021	1.3	EPA 200.8	7440-50-8
Lead	0.007	mg/L	0.001	05/14/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**  
May 11 2021  
EGLE-DWEHD-CWSS-LCU

## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ54650**  
**Work Order: 10500489\_03**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	552 BUENA VISTA, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/27/2021 10:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/05/2021 12:58
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	7.65	mg/L	0.05	05/10/2021	1.3	EPA 200.8	7440-50-8
Lead	0.469	mg/L	0.001	05/10/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 11 2021

EGLE-DWEHD-CWSS-LCU

## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ54651**  
**Work Order: 10500489\_04**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	552 BUENA VISTA, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/27/2021 10:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/05/2021 12:58
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	1.44	mg/L	0.05	05/10/2021	1.3	EPA 200.8	7440-50-8
Lead	0.143	mg/L	0.001	05/10/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 11 2021

EGLE-DWEHD-CWSS-LCU

## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ54677**  
**Work Order: 10500489\_30**

System Name/Owner: BENTON HARBOR  
Collection Address: 1037 PEARL, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/27/2021 13:00  
Date Received: 05/05/2021 12:58  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	1.30	mg/L	0.05	05/10/2021	1.3	EPA 200.8	7440-50-8
Lead	0.109	mg/L	0.001	05/10/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane





## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ54648  
Work Order: 10500489\_01

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1178 BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/29/2021 09:10
Sample Point:	BATHROOM SINK FIRST DRAW	Date Received:	05/05/2021 12:58
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.022	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ54649  
Work Order: 10500489\_02

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1178 BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/29/2021 09:10
Sample Point:	BATHROOM SINK FIFTH DRAW	Date Received:	05/05/2021 12:58
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.009	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ54652  
Work Order: 10500489\_05

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1237 COLUMBUS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/29/2021 08:30
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/05/2021 12:58
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.023	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ54653  
Work Order: 10500489\_06

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1237 COLUMBUS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/29/2021 08:30
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/05/2021 12:58
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: **LJ54654**  
Work Order: **10500489\_07**

System Name/Owner: BENTON HARBOR  
Collection Address: 857 OGDEN, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: BATHROOM SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/29/2021 07:25  
Date Received: 05/05/2021 12:58  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.010	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ54655  
Work Order: 10500489\_08

System Name/Owner: BENTON HARBOR  
Collection Address: 857 OGDEN, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: BATHROOM SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/29/2021 07:25  
Date Received: 05/05/2021 12:58  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.010	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ54656**  
**Work Order: 10500489\_09**

System Name/Owner: BENTON HARBOR  
Collection Address: 849 PIPESTONE, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/30/2021 06:30  
Date Received: 05/05/2021 12:58  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.009	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ54657  
Work Order: 10500489\_10

System Name/Owner: BENTON HARBOR  
Collection Address: 849 PIPESTONE, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/30/2021 06:30  
Date Received: 05/05/2021 12:58  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.008	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane





## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ54658  
Work Order: 10500489\_11

System Name/Owner: BENTON HARBOR  
Collection Address: 999 PEARL ST, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: BATHROOM SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/28/2021 23:30  
Date Received: 05/05/2021 12:58  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.008	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ54659  
Work Order: 10500489\_12

System Name/Owner: BENTON HARBOR  
Collection Address: 999 PEARL ST, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: BATHROOM SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/28/2021 23:30  
Date Received: 05/05/2021 12:58  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.009	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ54660  
Work Order: 10500489\_13

System Name/Owner: BENTON HARBOR  
Collection Address: 931 MONROE, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: BATHROOM SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/29/2021 06:45  
Date Received: 05/05/2021 12:58  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.009	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ54661**  
**Work Order: 10500489\_14**

System Name/Owner: BENTON HARBOR  
Collection Address: 931 MONROE, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: BATHROOM SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/29/2021 06:45  
Date Received: 05/05/2021 12:58  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.014	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ54662**  
**Work Order: 10500489\_15**

System Name/Owner: BENTON HARBOR  
Collection Address: 1110 OGDEN, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/27/2021 10:00  
Date Received: 05/05/2021 12:58  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ54663  
Work Order: 10500489\_16

System Name/Owner: BENTON HARBOR  
Collection Address: 1110 OGDEN, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/27/2021 10:00  
Date Received: 05/05/2021 12:58  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ54664  
Work Order: 10500489\_17

System Name/Owner: BENTON HARBOR  
Collection Address: 1129 JENNING, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/29/2021 07:00  
Date Received: 05/05/2021 12:58  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.009	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ54665  
Work Order: 10500489\_18

System Name/Owner: BENTON HARBOR  
Collection Address: 1129 JENNING, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/29/2021 07:00  
Date Received: 05/05/2021 12:58  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.012	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane





## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ54666  
Work Order: 10500489\_19

System Name/Owner: BENTON HARBOR  
Collection Address: 1240 PAVONE, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/27/2021 09:00  
Date Received: 05/05/2021 12:58  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ54667  
Work Order: 10500489\_20

System Name/Owner: BENTON HARBOR  
Collection Address: 1240 PAVONE, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/27/2021 09:00  
Date Received: 05/05/2021 12:58  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ54668  
Work Order: 10500489\_21

System Name/Owner: BENTON HARBOR  
Collection Address: 270 MAY ST, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/27/2021 08:00  
Date Received: 05/05/2021 12:58  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ54669  
Work Order: 10500489\_22

System Name/Owner: BENTON HARBOR  
Collection Address: 270 MAY ST, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/27/2021 08:00  
Date Received: 05/05/2021 12:58  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ54670  
Work Order: 10500489\_23

System Name/Owner: BENTON HARBOR  
Collection Address: 806 LASALLE, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/23/2021 09:00  
Date Received: 05/05/2021 12:58  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ54671  
Work Order: 10500489\_24

System Name/Owner: BENTON HARBOR  
Collection Address: 806 LASALLE, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/23/2021 09:00  
Date Received: 05/05/2021 12:58  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ54672  
Work Order: 10500489\_25

System Name/Owner: BENTON HARBOR  
Collection Address: 141 WINAN, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/29/2021 08:15  
Date Received: 05/05/2021 12:58  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ54673  
Work Order: 10500489\_26

System Name/Owner: BENTON HARBOR  
Collection Address: 141 WINAN, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/29/2021 08:15  
Date Received: 05/05/2021 12:58  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane





Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ54674**  
**Work Order: 10500489\_27**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1167 BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/29/2021 06:20
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	05/05/2021 12:58
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ54675  
Work Order: 10500489\_28

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	1167 BROADWAY, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/29/2021 06:20
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	05/05/2021 12:58
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ54676  
Work Order: 10500489\_29

System Name/Owner: BENTON HARBOR  
Collection Address: 1037 PEARL, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/27/2021 13:00  
Date Received: 05/05/2021 12:58  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.06	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.005	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ54678  
Work Order: 10500489\_31

System Name/Owner: BENTON HARBOR  
Collection Address: 660 MCGUIGAN, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/28/2021 13:06  
Date Received: 05/05/2021 12:58  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ54679  
Work Order: 10500489\_32

System Name/Owner: BENTON HARBOR  
Collection Address: 660 MCGUIGAN, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/28/2021 13:06  
Date Received: 05/05/2021 12:58  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ54680  
Work Order: 10500489\_33

System Name/Owner: BENTON HARBOR  
Collection Address: 174 HASTING, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/27/2021 08:00  
Date Received: 05/05/2021 12:58  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.013	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ54681  
Work Order: 10500489\_34

System Name/Owner: BENTON HARBOR  
Collection Address: 174 HASTING, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/27/2021 08:00  
Date Received: 05/05/2021 12:58  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



## Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

Sample ID: LJ54682  
Work Order: 10500489\_35

System Name/Owner: BENTON HARBOR  
Collection Address: 161 KLINE, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/29/2021 06:45  
Date Received: 05/05/2021 12:58  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane





Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ54683**  
**Work Order: 10500489\_36**

System Name/Owner: BENTON HARBOR  
Collection Address: 161 KLINE, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/29/2021 06:45  
Date Received: 05/05/2021 12:58  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/06/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	05/06/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53687**  
**Work Order: 10402998\_28**

System Name/Owner: BENTON HARBOR  
Collection Address: 732 MCALISTER, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/21/2021 14:00  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	05/03/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	05/03/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53660**  
**Work Order: 10402998\_01**

System Name/Owner: BENTON HARBOR  
Collection Address: 261 SEARLES, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/21/2021 11:00  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53661**  
**Work Order: 10402998\_02**

System Name/Owner: BENTON HARBOR  
Collection Address: 261 SEARLES, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/21/2021 11:00  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53662**  
**Work Order: 10402998\_03**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	718 TERRITORIAL, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/22/2021 10:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	04/28/2021 13:50
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.12	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.021	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53663**  
**Work Order: 10402998\_04**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	718 TERRITORIAL, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/22/2021 10:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	04/28/2021 13:50
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.65	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.107	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53664**  
**Work Order: 10402998\_05**

System Name/Owner: BENTON HARBOR  
Collection Address: 663 THRESHER, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/23/2021 13:20  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53665**  
**Work Order: 10402998\_06**

System Name/Owner: BENTON HARBOR  
Collection Address: 663 THRESHER, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/23/2021 13:20  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53666**  
**Work Order: 10402998\_07**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	366 MCCORD, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/21/2021 13:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	04/28/2021 13:50
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

**Sample Comment LJ53666** Sample did not meet collection volume requirements for test code CCUB when received at the lab. Container was not filled to the base of the neck per sample collection instructions. Result(s) may not be accepted for compliance purposes.

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.006	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53667**  
**Work Order: 10402998\_08**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	366 MCCORD, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/21/2021 13:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	04/28/2021 13:50
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

**Sample Comment LJ53667** Sample did not meet collection volume requirements for test code CCUB when received at the lab. Container was not filled to the base of the neck per sample collection instructions. Result(s) may not be accepted for compliance purposes.

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.008	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53668**  
**Work Order: 10402998\_09**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	534 E MAIN, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/21/2021 11:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	04/28/2021 13:50
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

**Sample Comment LJ53668** Sample did not meet collection volume requirements for test code CCUB when received at the lab. Container was not filled to the base of the neck per sample collection instructions. Result(s) may not be accepted for compliance purposes.

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53669**  
**Work Order: 10402998\_10**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	534 E MAIN, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/21/2021 11:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	04/28/2021 13:50
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

**Sample Comment LJ53669** Sample did not meet collection volume requirements for test code CCUB when received at the lab. Container was not filled to the base of the neck per sample collection instructions. Result(s) may not be accepted for compliance purposes.

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53670**  
**Work Order: 10402998\_11**

System Name/Owner: BENTON HARBOR  
Collection Address: 150 PARKER, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/22/2021 06:00  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.005	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53671**  
**Work Order: 10402998\_12**

System Name/Owner: BENTON HARBOR  
Collection Address: 150 PARKER, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/22/2021 06:00  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

Official Laboratory Report

**RECEIVED**  
May 4 2021  
EGLE-DWEHD-CWSS-LCU

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53672**  
**Work Order: 10402998\_13**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	807 HIGH,BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/22/2021 14:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	04/28/2021 13:50
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	1.29	mg/L	0.05	05/03/2021	1.3	EPA 200.8	7440-50-8
Lead	0.605	mg/L	0.001	05/03/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U .S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53673**  
**Work Order: 10402998\_14**

System Name/Owner: BENTON HARBOR  
Collection Address: 807 HIGH, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/22/2021 14:00  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.69	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.145	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53674**  
**Work Order: 10402998\_15**

System Name/Owner: BENTON HARBOR  
Collection Address: 797 WAUCEDA, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/21/2021 15:00  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.004	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53675**  
**Work Order: 10402998\_16**

System Name/Owner: BENTON HARBOR  
Collection Address: 797 WAUCEDA, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/21/2021 15:00  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53676**  
**Work Order: 10402998\_17**

System Name/Owner: BENTON HARBOR  
Collection Address: 127 SEARLES, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/22/2021 08:00  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53677**  
**Work Order: 10402998\_18**

System Name/Owner: BENTON HARBOR  
Collection Address: 127 SEARLES, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/22/2021 08:00  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53678**  
**Work Order: 10402998\_19**

System Name/Owner: BENTON HARBOR  
Collection Address: 754 LAVETTE, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/21/2021 02:30  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53679**  
**Work Order: 10402998\_20**

System Name/Owner: BENTON HARBOR  
Collection Address: 754 LAVETTE, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/21/2021 02:30  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.09	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53680**  
**Work Order: 10402998\_21**

System Name/Owner: BENTON HARBOR  
Collection Address: 711 BUSS, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/21/2021 16:00  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53681**  
**Work Order: 10402998\_22**

System Name/Owner: BENTON HARBOR  
Collection Address: 711 BUSS, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/21/2021 16:00  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53682**  
**Work Order: 10402998\_23**

System Name/Owner: BENTON HARBOR  
Collection Address: 759 BUSS, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/21/2021 06:00  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53683**  
**Work Order: 10402998\_24**

System Name/Owner: BENTON HARBOR  
Collection Address: 759 BUSS,BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/21/2021 06:00  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U .S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53684**  
**Work Order: 10402998\_25**

System Name/Owner: BENTON HARBOR  
Collection Address: 277 HASTINGS, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/22/2021 09:00  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.002	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53685**  
**Work Order: 10402998\_26**

System Name/Owner: BENTON HARBOR  
Collection Address: 277 HASTINGS, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/22/2021 09:00  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.003	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53686**  
**Work Order: 10402998\_27**

System Name/Owner: BENTON HARBOR  
Collection Address: 732 MCALISTER, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/21/2021 14:00  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53688**  
**Work Order: 10402998\_29**

System Name/Owner: BENTON HARBOR  
Collection Address: 140 BENTON, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/23/2021 10:00  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.11	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53689**  
**Work Order: 10402998\_30**

System Name/Owner: BENTON HARBOR  
Collection Address: 140 BENTON, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/23/2021 10:00  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	0.20	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53690**  
**Work Order: 10402998\_31**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	810 NATE WELLS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/21/2021 17:00
Sample Point:	KITCHEN SINK FIRST DRAW	Date Received:	04/28/2021 13:50
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

**Sample Comment LJ53690** Sample did not meet collection volume requirements for test code CCUB when received at the lab. Container was not filled to the base of the neck per sample collection instructions. Result(s) may not be accepted for compliance purposes.

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53691**  
**Work Order: 10402998\_32**

System Name/Owner:	BENTON HARBOR	WSSN/Pool ID:	0600
Collection Address:	810 NATE WELLS, BENTON HARBOR	Source:	TYPE I
Collected By:	RESIDENT	Site Code:	DIST
Township/Well#/Section:	//	Collector:	Other
County:	Berrien	Date Collected:	04/21/2021 17:00
Sample Point:	KITCHEN SINK FIFTH DRAW	Date Received:	04/28/2021 13:50
Water System:	Treated Public Distribution System	Purpose:	Routine Monitoring

**Sample Comment LJ53691** Sample did not meet collection volume requirements for test code CCUB when received at the lab. Container was not filled to the base of the neck per sample collection instructions. Result(s) may not be accepted for compliance purposes.

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County  
2149 E. Napier Ave.  
Benton Harbor, MI 49022  
269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53692**  
**Work Order: 10402998\_33**

System Name/Owner: BENTON HARBOR  
Collection Address: 753 BROADWAY, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/21/2021 14:00  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53693**  
**Work Order: 10402998\_34**

System Name/Owner: BENTON HARBOR  
Collection Address: 753 BROADWAY, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/21/2021 14:00  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53694**  
**Work Order: 10402998\_35**

System Name/Owner: BENTON HARBOR  
Collection Address: 792 BRITAIN, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/22/2021 11:00  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	0.001	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53695**  
**Work Order: 10402998\_36**

System Name/Owner: BENTON HARBOR  
Collection Address: 792 BRITAIN, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/22/2021 11:00  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53696**  
**Work Order: 10402998\_37**

System Name/Owner: BENTON HARBOR  
Collection Address: 427 FOSTER, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIRST DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/21/2021 13:24  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane

**RECEIVED**

May 3 2021

EGLE-DWEHD-CWSS-LCU

### Official Laboratory Report

Report To: ROBERT JONES  
601 N RIDGEWAY CT  
ST JOSEPH MI 49085

**Sample ID: LJ53697**  
**Work Order: 10402998\_38**

System Name/Owner: BENTON HARBOR  
Collection Address: 427 FOSTER, BENTON HARBOR  
Collected By: RESIDENT  
Township/Well#/Section: //  
County: Berrien  
Sample Point: KITCHEN SINK FIFTH DRAW  
Water System: Treated Public Distribution System

WSSN/Pool ID: 0600  
Source: TYPE I  
Site Code: DIST  
Collector: Other  
Date Collected: 04/21/2021 13:24  
Date Received: 04/28/2021 13:50  
Purpose: Routine Monitoring

TESTING INFORMATION					REGULATORY INFORMATION		
Analyte Name	Result	Units	RL	Date Tested	MCL/AL	Method	CAS #
Copper	Not detected	mg/L	0.05	04/29/2021	1.3	EPA 200.8	7440-50-8
Lead	Not detected	mg/L	0.001	04/29/2021	0.015	EPA 200.8	7439-92-1

The analyses performed by the EGGLE Drinking Water Laboratory were conducted using methods approved by the U.S. Environmental Protection Agency in accordance with the Safe Drinking Water Act, 40 CFR parts 141-143, and other regulatory agencies as appropriate.

**Your local health department has detailed information about the quality of drinking water in your area. If you have concerns about the health risks related to the test results of your sample, please contact the Environmental Health Section through the address and telephone number listed below.**

**Berrien County**  
**2149 E. Napier Ave.**  
**Benton Harbor, MI 49022**  
**269 927-5623**

RL: Reporting Limit  
MCL: Maximum Contaminant Level  
AL: Action Level  
Not Detected: Not detected at or above the reporting limit (RL)

mg/L: milligrams / Liter (ppm)  
ng/L: nanograms / Liter (ppt)  
MPN: Most Probable Number

CFU: Colony Forming Unit  
CAS: Chemical Abstract Service  
Laboratory Contact: Marlene Kane



WSSN 0600

The City of Benton Harbor and F&V Operations and Resource Management are submitting the following report(s) to Michigan Department of Environment, Great Lakes and Energy:

Lead Copper Report H1 2021

*"I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the persons or persons who manage the system or those persons directly responsible for gathering such information, the information submitted is to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations."*

F&V Operations Representative: Robert Jones

Signature:

Date:

7/9/21





MICHIGAN DEPARTMENT OF ENVIRONMENT, GREAT LAKES, AND ENERGY  
DRINKING WATER AND ENVIRONMENTAL HEALTH DIVISION

**LEAD AND COPPER REPORT AND  
CONSUMER NOTICE FOR COMMUNITY WATER SUPPLY  
FORM A – SUPPLIES WITH LEAD SERVICE LINES**

*Issued under authority of the Michigan Safe Drinking Water Act, 1976 PA 399,  
as amended (Act 399), MCL 325.1001 et seq., and the Administrative Rules.*

*Failure to submit this information is a violation of Act 399 and may subject the water supply to enforcement penalties.*

Administrative Rule R 325.10710d requires water supplies to report lead and copper monitoring information within ten days after the end of the monitoring period. This form may be used to meet this requirement. Form instructions are available on pages 8 - 10. Submit the information to the appropriate Michigan Department of Environment, Great Lakes, and Energy (EGLE) district office.

1. Supply Name: City of Benton Harbor  
 2. County: Berrien 3. WSSN: 0600  
 4. Population: 9,828 5. Monitoring Period: From: 1/01/2021 To: 06/30/2020  
 6. Minimum # of Samples Required: 60 7. # of Samples Taken: 84  
 8. Name of Certified Laboratory: State of Michigan

9. SAMPLE CRITERIA:

This form is for water supplies collecting <u>some</u> or <u>all</u> lead and copper samples from sites WITH LEAD SERVICE LINES. All other supplies should use Form B.		
Yes	No	
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Are some or all samples from sites WITH lead service lines? If no sites served by a lead service line, STOP and use Form B.
<input checked="" type="checkbox"/>	<input type="checkbox"/>	Did you prioritize sample collection according to the following: <ul style="list-style-type: none"> <li>• Tier 1 sites must be used unless insufficient Tier 1 sites available.</li> <li>• If insufficient Tier 1 sites available, then Tier 2 sites must be used.</li> <li>• If insufficient Tier 2 sites, then Tier 3 sites must be used.</li> <li>• If no Tier 1, 2, or 3 sites are available, sites must be representative of plumbing materials typically found throughout the water system.</li> </ul>
<input type="checkbox"/>	<input checked="" type="checkbox"/>	Were the same sampling sites used as in the previous monitoring period? If no, explain (attach additional pages if needed): recently documented lead service line addresses were prioritized and then previously sampled locations
Comments:		

10. SIGNATURE:

Name: Robert Jones

Signature: 

Title: \_\_\_\_\_

Phone: 8102209441

Date: 07/09/2021

# WSSN 0600 City of Benton Harbor 1st Half 2021

Lead and Copper Report and Consumer Notice for Community Water Supply Form A -Supplies with Lead Service Leads											
Sample Location	Sample Date	Tier (1,2, 3, OT)	Category	Building Plumbing	Service Line (L, C, G, P)		Tap Type (K, B)	1st Draw		5th Draw	
								Lead ppb	Copper ppb	Lead ppb	Copper ppb
261 Searles	04/21/21	1	A	11	L		K	ND	ND	ND	ND
718 Territorial	04/22/21	1	A	19	L		K	21	120	107	650
663 Thresher	04/23/21	1	A	17	L		K	1	ND	ND	ND
150 Parker	04/22/21	1	A	8	L		K	5	ND	2	ND
807 High	04/22/21	1	A	27	L		K	605	1290	145	690
797 Wauceda	04/21/21	1	A	25	L		K	4	ND	3	ND
127 Searles	04/22/21	1	A	5	L		K	2	ND	3	ND
754 Lavette	04/21/21	1	A	22	L		K	2	ND	ND	90
711 Buss	04/21/21	1	A	18	L		K	ND	ND	ND	ND
759 Buss	04/21/21	1	A	23	L		K	3	ND	1	ND
277 Hastings	04/22/21	1	A	12	L		K	2	ND	3	ND
732 McAlister	04/21/21	1	A	20	L		K	1	ND	2	ND
140 Benton	04/23/21	1	A	7	L		K	ND	110	ND	200
753 Broadway	04/21/21	1	A	21	L		K	ND	ND	1	ND
792 Britain	04/22/21	1	A	24	L		K	1	ND	ND	ND
1178 Broadway	04/29/21	1	A	41	L		K	22	ND	9	ND
1237 Columbus	04/29/21	1	A	47	L		K	23	ND	4	ND
857 Ogden	04/29/21	1	A	42	L		B	10	ND	10	ND
999 Pearl	04/28/21	1	A	40	L		B	8	ND	9	ND
931 Monroe	04/29/21	1	A	31	L		B	9	ND	14	ND
1110 Ogden	04/27/21	1	A	64	L		K	ND	ND	3	ND
1129 Jennings	04/29/21	1	A	32	L		K	9	ND	12	ND
806 Lasalle	04/23/21	1	A	26	L		K	ND	ND	ND	ND
141 Winan	04/29/21	1	A	43	L		K	ND	ND	ND	ND
1167 Broadway	04/29/21	1	A	61	L		K	1	ND	ND	ND



660 McGuigan	04/28/21	1	A	60	L	K	ND	ND	ND	ND
174 Hasting	04/27/21	1	A	34	L	K	13	ND	2	ND
161 Kline	04/29/21	1	A	63	L	K	4	ND	ND	ND
552 Buena Vista	04/27/21	1	A	53	L	K	469	7650	143	1440
582 Niles	05/06/21	1	A	59	L	K	2	ND	2	ND
1264 Pavone	05/04/21	1	A	45	L	K	2	ND	ND	ND
817 Nate Wells	05/06/21	1	A	29	L	K	7	110	3	80
1248 Broadway	05/07/21	1	A	33	L	K	2	ND	2	ND
191 Searles	05/06/21	1	A	9	L	K	ND	ND	ND	ND
1086 Superior	05/05/21	1	A	35	L	K	ND	ND	ND	ND
208 Seeley	05/06/21	1	A	10	L	K	ND	ND	ND	ND
781 Buss	05/06/21	1	A	39	L	K	41	ND	4	ND
166 Searles	05/06/21	1	A	46	L	K	18	ND	16	ND
341 Brunson	05/07/21	1	A	49	L	K	ND	ND	ND	ND
596 Cass	05/14/21	1	A	16	L	K	ND	ND	ND	ND
1274 Ogden	05/18/21	1	A	6	L	K	ND	ND	ND	ND
1118 Broadway	05/18/21	1	A	3	L	K	6	ND	5	ND
446 Packard	05/18/21	1	A	14	L	K	1	ND	ND	ND
578 Edwards	05/18/21	1	A	48	L	B	ND	ND	ND	ND
1165 Hannah	05/14/21	1	A	4	L	K	2	60	1	ND
566 Territorial	05/17/21	1	A	65	L	K	1	ND	1	ND
1037 Pearl	05/18/21	1	A	58	L	K	1	ND	1	ND
1037 Pearl	04/27/21	1	A	58.5	L	K	5	600	109	1300
366 McCord	04/21/21	1	A	13	L	K	6	ND	8	ND
534 E Main	04/21/21	1	A	15	L	K	ND	ND	ND	ND
1022 Hurd	05/18/21	1	A	2	L	K	ND	ND	ND	ND
810 Nate Wells	04/21/21	1	A	29	L	K	ND	ND	ND	ND
946 BISHOP	06/22/21	1	A	30	L	K	2	ND	1	ND
285 Hastings	06/24/21	1	A	34	L	K	1	ND	1	ND
1112 Agard	06/22/21	1	A	37	L	K	28	ND	2	ND
1020 Bishop	06/22/21	1	A	38	L	K	ND	ND	ND	ND
768 Broadway	06/24/21	1	A	44	L	K	ND	ND	ND	ND
1191 Pavone	06/22/21	1	A	50	L	B	ND	ND	2	ND
1225 Colfax	06/22/21	1	A	51	L	K	3	ND	2	ND
1161 Union St	06/22/21	1	A	52	L	K	7	ND	7	ND
1143 Union	06/22/21	1	A	54	L	K	ND	ND	ND	ND

201 Garfield	06/22/21	1	A	55	L	K	6	ND	14	ND
204 Garfield	06/22/21	1	A	56	L	B	ND	ND	ND	ND
1043 Agard	06/22/21	1	A	57	L	B	3	ND	9	ND
1066 Monroe	06/22/21	1	A	62	L	B	ND	ND	4	ND
427 Foster	04/21/21	unknown				K	ND	ND	ND	ND
849 Pipestone	04/30/21	unknown				K	9	ND	8	ND
1240 Pavone	04/27/21	unknown				K	ND	ND	ND	ND
270 May	04/27/21	unknown				K	4	ND	ND	ND
626 Territorial	05/06/21	unknown				K	390	350	4	70
558 Niles	05/07/21	unknown				K	2	50	2	50
717 Highland	05/06/21	unknown				K	11	130	11	120
1111 Superior	05/06/21	unknown				K	ND	ND	ND	ND
152 Lake	05/06/21	unknown				K	ND	ND	ND	ND
1152 Monroe	05/06/21	unknown				K	1	ND	ND	ND
1173 Lavette	05/06/21	unknown				K	1	ND	4	ND
1034 Broadway	05/06/21	unknown				K	ND	ND	ND	ND
823 Lavette	05/06/21	unknown				K	ND	ND	ND	ND
1046 Broadway	05/07/21	unknown				K	889	1433	7	80
1008 Pearl	05/18/21	unknown				K	ND	ND	ND	ND
507 Britain	05/18/21	unknown				K	ND	ND	ND	ND
1063 Columbus	05/18/21	unknown				K	6	ND	6	ND
246 Pipestone	03/01/21	unknown				K	ND	ND	ND	ND
823/623 Lavette	06/23/21	unknown				K	ND	ND	ND	ND