





Legend

- ▲ Soil XRF Sample Exceeds Part 201 Residential Direct Contact Criteria (RDCC)
- Orange box: XRF results exceeding RDCC are shown in Orange
- Yellow box: Laboratory results exceeding RDCC are shown in Yellow
- J -- Data qualified as estimated based on data validation
- * -- Analyte detected below quantitation limits
- mg/kg -- milligrams per kilogram

Source of Imagery: ESRI ArcGIS Map Service (c) 2007
Date of Photography: 06/21/2005



Prepared for:
U.S. EPA REGION V
Contract No: EP-S5-06-04

TDD No.: S05-0002-0708-020
DCN: 274-2A-ABDT





Prepared by:
WESTON SOLUTIONS, INC.
2501 Jolly Road, Suite 100
Okemos, Michigan

AOI Nos. 7 and 15
RDCC EXCEEDANCES IN SOIL
TORCH LAKE AREA ASSESSMENT
KEWEENAW PENINSULA, MICHIGAN
October 2007

Figure 2b



Source of Imagery: ESRI ArcGIS Map Service (c) 2007
Date of Photography: 06/21/2005



Legend

- ▲ START XRF and Laboratory Sample
- ▲ START XRF Sample
- ◆ Water Edge
- ◆ GPS Feature - Other
- - - Fenced Area
- Lake Edge

File: \\FSOMI01\GIS\GIS_P\Projects\Lake_Linden\mxdslFinal_AA\Fig3a-DollarBay(11-13-07).mxd, 13-Nov-07 07:37, BROWNK



Prepared for:
U.S. EPA REGION V
Contract No: EP-S5-06-04

TDD No.: S05-0002-0708-020
DCN: 274-2A-ABDT



Prepared by:
WESTON SOLUTIONS, INC.
2501 Jolly Road, Suite 100
Okemos, Michigan

AOI Nos. 16 and 17
SITE FEATURES AND XRF LOCATIONS
TORCH LAKE AREA ASSESSMENT
KEWEENAW PENINSULA, MICHIGAN
October 2007

Figure 3a