



Legend

- ▲ FIELDS Team XRF and Laboratory Sample
- ▲ FIELDS Team XRF Sample
- ▲ START XRF and Laboratory Sample
- ▲ START XRF Sample
- ◆ Debris Pile/Drums
- ◆ Water Edge
- ◆ GPS Feature - Other
- MDEQ Identified Drums/Debris
- Debris Area

Source of Imagery: ESRI ArcGIS Map Service (c) 2007
Date of Photography: 06/21/2005



Prepared for:
U.S. EPA REGION V
Contract No: EP-S5-06-04

TDD No.: S05-0002-0708-020
DCN: 274-2A-ABDT





Prepared by:
WESTON SOLUTIONS, INC.
2501 Jolly Road, Suite 100
Okemos, Michigan

AOI Nos. 12 and 23
SITE FEATURES AND XRF LOCATIONS
TORCH LAKE AREA ASSESSMENT
KEWEENAW PENINSULA, MICHIGAN
October 2007

Figure 8a



Source of Imagery: ESRI ArcGIS Map Service (c) 2007
Date of Photography: 06/21/2005



Legend

- ▲ Soil XRF Sample Exceeds Part 201 Residential Direct Contact Criteria (RDCC)
- Orange box: XRF results exceeding RDCC are shown in Orange
- Yellow box: Laboratory results exceeding RDCC are shown in Yellow
- mg/kg -- milligrams per kilogram



Prepared for:
U.S. EPA REGION V
Contract No: EP-S5-06-04

TDD No.: S05-0002-0708-020
DCN: 274-2A-ABDT



Prepared by:
WESTON SOLUTIONS, INC.
2501 Jolly Road, Suite 100
Okemos, Michigan

AOI Nos. 12 and 23
RDCC EXCEEDANCES IN SOIL
TORCH LAKE AREA ASSESSMENT
KEWEENAW PENINSULA, MICHIGAN
October 2007

Figure 8b