



EGLE Part 213 DAILY REPORT – October 8, 2021

Incident Name: Flat Rock ER 08-31-2021

Ford Flat Rock Assembly Facility

Gasoline Release

1 International Drive, Flat Rock, Michigan

To: Paul Owens (EGLE)

REF. No.: REL-0186-21

CC: Ford Motor Company (Ford)

DATE: October 8, 2021

October 8, 2021

- Ford contractors continued to maintain culvert plug in the 10” sanitary line on Ford property
 - Ford contractors continued to remove sanitary water from the plugged sanitary line and stage the liquid on-site temporary frac tank storage
 - Ford contractors collected one sample of liquid from the 10” sanitary line for laboratory analysis
- Ford contractors continued monitoring containment boom within stormwater pond as a proactive measure
- Ford contractors continued excavation activities along the north and west sides of the existing excavation on Ford Property
- Ford contractors completed a sub slab vapor intrusion assessment inside the plant adjacent to the release area. ***Fifteen (15) soil gas samples, plus one duplicate, were collected.***
- Ford contractors completed vacuuming and flushing activities of the drain tile network at the Hickory residence
- Ford contractors continued implementing activities of the re-occupancy plan
 - Prescreening activities of one (1) Category 3 residence
 - Sampling activities of one (1) Category 1 residence
 - Post screening activities of one (1) Category 3 residence

Tactics October 8, 2021 (19:00) to October 9, 2021 (19:00)

- Ford contractors will continue to maintain the culvert plug in the 10” sanitary line on Ford property
 - Ford contractors will continue to remove sanitary water from the plugged sanitary line and stage the liquid on-site temporary frac tank storage
 - Ford contractors will collect one sample of liquid from the 10” sanitary line for laboratory analysis
- Ford contractors will continue to monitor containment boom within stormwater pond as a proactive measure
- Ford contractors will continue implementing activities of the re-occupancy plan
 - Sampling activities of one (1) Category 3 residence