



- LEGEND**
- MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY MONITORING WELL
 - ABANDONED MICHIGAN DEPARTMENT OF ENVIRONMENTAL QUALITY MONITORING WELL
 - MONITORING/OBSERVATION WELL
 - ABANDONED OBSERVATION WELL
 - PUMPING WELL
 - FORMER KELSEY-HAYES PROPERTY BOUNDARY
 - RAILROAD TRACK
 - FENCE LINE
 - GROUNDWATER TREATMENT SYSTEM UNDERGROUND ELECTRICAL
 - GROUNDWATER TREATMENT SYSTEM UNDERGROUND ELECTRICAL AND CONVEYANCE PIPING
 - GROUNDWATER TREATMENT SYSTEM UNDERGROUND CONVEYANCE PIPING
 - GROUNDWATER TREATMENT SYSTEM UNDERGROUND DISCHARGE PIPING

- GROUNDWATER TREATMENT SYSTEM UNDERGROUND ELECTRICAL
- GROUNDWATER TREATMENT SYSTEM UNDERGROUND ELECTRICAL AND CONVEYANCE PIPING
- GROUNDWATER TREATMENT SYSTEM UNDERGROUND CONVEYANCE PIPING
- GROUNDWATER TREATMENT SYSTEM UNDERGROUND DISCHARGE PIPING

GWTS - Groundwater Treatment System



FORMER KELSEY-HAYES PLANT
MILFORD, MICHIGAN

SITE LAYOUT

FIGURE
1

Service Layer Credits: Source: Esri, DigitalGlobe, GeoEye, Earthstar Geographics, CNES/Airbus DS, USDA, USGS, AeroGRID, IGN, and the GIS User Community