

**MICHIGAN DEPARTMENT OF LICENSING  
AND REGULATORY AFFAIRS  
BUREAU OF FIRE SERVICES - STORAGE TANK DIVISION**

**Public Record - Summary Information of Underground Storage Tanks (USTs)**

**General Information**

**Posted Date: December 26, 2023**

Total Number of UST Facilities: 6,283  
Total Number of USTs: 16,642

**Summary Information for On-Site Inspections**

Number of UST Facilities Inspected: 2,136  
Inspection Period Dates: **10/1/2022** to: **9/30/2023**  
Percent Compliance (Combined Measure): Data Not Available<sup>1</sup>

Note: Tank, facility and on-inspection information is base on [Michigan Underground Storage Tank Rules \(MUSTR\)](#)

On-site inspections measures compliance with Site Assessments for Underground Storage Tank Systems

**Summary Information for Releases**

Number of Confirmed UST Releases: 207  
Release Reporting Period Dates: **10/1/2022** to: **9/30/2023**

**Summary Information for Release Sources and Causes**

Source			Cause													
			Spill		Overfill		Phys/Mech Damage		Corrosion		Install Problem		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	34	16.4%					34	49%								
Piping	35	16.9%					35	51%								
Dispenser	11	5.3%											11	64.7%		
STP																
Delivery Problem	2	1.0%			2	40%										
Other	9	4.4%			3	60%							6	35.3%		
Unknown	116	56.0%													116	100%
Totals	207	100%			5	100%	69	100%					17	100%	116	100%

# =number, % =percent of total number

Note: Release, source, and cause information is based on [Michigan Underground Storage Tank Rules \(MUSTR\)](#)  
Source and cause data were collected using the rules for site characterization and cleanup as given in [Part 213, Leaking Underground Storage Tanks \(LUST\)](#), of the Natural Resources and Environmental Protection 1994 PA 451, as amended.  
Obtain site-specific UST information [Underground Storage Tank List](#).

<sup>1</sup> Due to database calculation issues identified, BFS is working with DTMB to correct the calculations.