



FIGURE 5: CONTAMINANTS CONCENTRATIONS IN GROUNDWATER SAMPLE
1700 EAST FRONT STREET
MONROE, MICHIGAN

PROJECT NO.: 19040
DATE: MARCH 14, 2022

DR: bhu
CAD FILE: 19040EV-1



DARCY ENVIRONMENTAL
(313) 264-1216
www.darcyenvironmental.com
OFFICES IN NORTH AMERICA AND ASIA