





LEGEND

- Green indicates PFAS compounds are non-detect
- ▲ Yellow indicates one or more of the PFAS Substances detected below criteria
- Red indicates PFAS compounds exceed criteria
- ➔ Groundwater flow direction
- ★ MPART Site
- MW - Monitoring Well



AERIAL PHOTO SOURCE: NEARMAP

0 15 30 60 Meters
 0 70 140 280 Feet
 1:3,241



Anderson LF LOCATION ID 63000005 50250 Eight Mile Road NORTHVILLE TOWNSHIP, OAKLAND COUNTY T01N R08E SECTION 31		
Site Map		
GEOLOGIST Ira Adolphues Field Operations Services		CREATION DATE June 2026
Remediation and Redevelopment Division		FIGURE 1